Guidelines on creating worklists for pooling in Native Barcoding Sequencing Kit

1. Pooling destinations must be a continuous sequence. No gaps allowed between pools.



2. Each pool must contain an equal number of samples to each other pool.

3. There must a minimum of 6 samples per pool.

4. Make sure the CSV file has no empty rows, including the final row.