



FUTURA PRO NEWS WEB



Software version **Futura PRO 3.51.0 - DB 13.00**- Silca APP version 3.0

Please refer to the machine manual for the operations to follow.

*The updated software operator's guide for FUTURA PRO is available on the Silca website (www.silca.biz)
within the **KEY CUTTING MACHINES** section*

MARCH 2025

1_2025 FUTURA PRO V.3.51.0

NEW SYSTEMS

	LOCK MANUFACTURER	LOCK SYSTEM	PROFILE	SERIES	SN	DATA CARD	CLAMP	CUTTER
	ASSA ABLOY	Assa Abloy (5P)		01234567 89	10040	5577	01V	01F
	ASSA ABLOY	Assa Abloy (6P)		01234567 89	10041	5578	01V	01F
	EVVA	Evva DPX (Lateral cut)	-	-	2534	5569	01R-24J-25J	23D
	ICSA	Icsa S6 (P6)	-	-	2546	5594	01R-01J-02J	01D
	ICSA	Icsa SGK Modello S2/S3	C.....	000001- 107604	10037	5410	01V	01F
	ISEO	Iseo R6 (6P)	AEA.....	000001- 037376	2547	869	01R-01J-02J	01D
	LINCE 	Lince C5X Interp. (5+5+5)	-	-	1190	3074	01R-152-153	30D
	OMEC	Omec Serie 240			2541	5589	01R-01J-02J	01D
	TESA 	Tesa T60/T80-3D PL1-16	-	-	2542	5590	01R-01J-02J	09D
	TITAN 	HSH	-	-	2544	5551	01R-01J-02J	02D
	ZEISS-IKON	Zeiss-Ikon VRS (6P)		12345678 90ABCD EFGHIL	10038	5580	12V-R	01F
	ZEISS-IKON	Zeiss-Ikon VRS Mirrored (6P)		12345678 90ABCD EFGHIL	10039	5581	12V-L	01F



FUTURA PRO NEWS WEB



DECEMBER 2024

1_2024 FUTURA/FUTURA PRO V.3.50.0



Fixed the corrections of the adapters.

DECEMBER 2024

1_2024 FUTURA PRO V.3.50.0

NEW SYSTEMS

	LOCK MANUFACTURER	LOCK SYSTEM	PROFILE	SERIES	SN	DATA CARD	CLAMP	CUTTER
	IFAM	Ifam PLATINUM M - IRIIDIUM M (MKS)	-	-	2535	5570	01R-01J-02J	01D
	OMEC	Omec Serie 220	AC.....	0000001 - 0046656	2532	5567	01R-01J-02J	01D
	PIAGGIO	Piaggio (2T-7W)	-	-	2538	5573	01R-01J-02J 01R-106-107	01LW
	SECURYSTAR 	SECURYSTAR Mobile Code 20L/21L	-	-	2531	5563	09R	29DW
	SECURYSTAR 	SECURYSTAR Mobile Code 50/51/53	-	-	2530	5562	09R	29DW
	SECURYSTAR 	SECURYSTAR Extra Safe +/-1	-	-	2529	5561	09R	29DW
	SECURYSTAR 	SECURYSTAR Pro Star New	-	-	2528	5560	09R	29DW
	SECURYSTAR 	SECURYSTAR Pro Star-Mobile Code 50/51/53	-	-	2527	5559	09R	29DW
	STAR 	Star 80S (4+4)	...-xxxxxx	135-458	2533	5568	01R-01J-02J	02D
	STAR	Star 80S (5P)		13500001 - 45816675	10036	606	01V	01F
	THIRARD 	Thirard Transit 2 (Fiche 2)	-	-	2537	5572	01R-01J-02J	19D
	THIRARD 	Thirard Transit 2 (Fiche 3)	-	-	2536	5571	01R-01J-02J	19D

NOVEMBER 2024

1_2024 FUTURA/FUTURA PRO V.3.49.1



FUTURA PRO NEWS WEB



- Solved a problem related to importing user series .
- Fixed cutting problem on key ASS196R card 5172

OCTOBER 2024

1_2024 FUTURA PRO V.3.49.0

NEW SYSTEMS

	LOCK MANUFACTURER	LOCK SYSTEM	PROFILE	SERIES	SN	DATA CARD	CLAMP
	BASI - DOM 	Basi SPK (Prf. 161)	-	-	1444	3695	01R-01J-02J
	KESO	Keso K1000 (5 Axis)	-	-	2523	5555	01R-26J-27J
	KESO	Keso K1000S (5 Axis)	-	-	2521	5553	01R-26J-27J
	KESO	Keso K1000S (Step drilling) (4 Axis)	-	-	2522	5554	01R-26J-27J
	KESO	Keso K2000S (3mm) Step drilling (4 Axis)	-	-	2520	5552	01R-01J-02J
	KESO	Keso K2000S (5mm) Step drilling (4 Axis)	-	-	2519	5549	01R-01J-02J
	KESO	Keso K3000 (Step drilling) (4 Axis)	-	-	2512	5548	01R-26J-27J
	KIA	EV9	MV....	0001-2254	2518	3911	01R-01J-02J 01R-106-107
	MOLLOCK - ICSA	217/M		1234567	10035	5550	01V
	TARONI	SERIE 2.2		501001-501648	2517	4504	01R-01J-02J
	TARONI	SERIE 3D NEXT 5P	5N....	0001-2074	2513	5066	01R-01J-02J
	TARONI	SERIE 3D NEXT 6P	6N.....	00001-12678	2514	5066	01R-01J-02J
	TARONI	SERIE 3S NEXT 5P	5N....	0001-2074	2515	5067	01R-01J-02J
	TARONI	SERIE 3S NEXT 6P	6N.....	00001-12678	2516	5067	01R-01J-02J

JULY 2024

1_2024 FUTURA PRO V.3.48.0



FUTURA PRO NEWS WEB



NEW SYSTEMS

	LOCK MANUFACTURER	LOCK SYSTEM	PROFILE	SERIES	SN	DATA CARD	CLAMP
	DABEL	CL2040 (6P)	-	-	2509	5545	01R-01J-02J
	DABEL	KA2011K (6P)	-	-	2510	5546	01R-01J-02J
	DABEL	KA2035K (6P)	-	-	2511	5547	01R-01J-02J
	DORIC	-		27001-27400	10033	5543	01V
	MUL.T.LOCK	Mul.T.Lock Interactive +	(115S)	-	2507	1850	01R-01J-02J
	NIMLY	Nimly (6+5)	-	-	2508	5542	01R-01J-02J
	SANDLEFORD	-		123	10034	5544	01V
	SKS	SKS1R (6P)	-	-	8607	2581	01V
	YALE	Yale 1100-1300		000001-030302	2506	5541	01R-05J-06J

JUNE 2024

1_2024 FUTURA PRO V.3.47.0

NEW SYSTEMS

	LOCK MANUFACTURER	LOCK SYSTEM	PROFILE	SERIES	SN	DATA CARD	CLAMP
	ABUS	CSI-KB68 (2T-6W)	-	-	2465	5529	01R-01J-02J
	ERREBI	LOK 2000 (5+4)	-	-	2501	5530	01R-01J-02J
	EVVA 	DPI (Lateral cut)	-	-	2503	5532	01R-01J-02J
	EVVA 	EPS (Lateral cut)	-	-	2502	5537	01R-01J-02J
	GUARD	Profile FPS-NP System 34F	34F.....	00001-99999	10032	666	01V
	GUARD	Profile G18 System 27T	27T.....	00001-99999	10031	666	01V
	OMEC 	OMEC OTTO		0000000000- ZZZZZZZZZZ	2505	5536	01R-05J-06J



FUTURA PRO NEWS WEB



APRIL 2024

1_2024 FUTURA PRO V.3.46.0

NEW SYSTEMS

	LOCK MANUFACTURER	LOCK SYSTEM	PROFILE	SERIES	SN	DATA CARD	CLAMP
	AMIG 	Amig 9645 (6+6+5)	J.....	0000001-0001080	2492	5518	01R-01J-02J
	FTH THIRARD	Fth Trafic 6	-	-	2487	5512	01R-05J-06J
	HUF	VW HU66P (2T-8W)		1-2000	2493	5519	01R-19J-02J
	HUF	VW HU66P (2T-8W)		1-3321	2491	970	01R-19J-02J
	IFAM	Start R (6P)	-	-	2478	5509	01R-01J-02J
	IFAM	Start S (5P)		12345	10028	5508	01V
	KIA	Kia (2T-8W)	KA....	0001-2500	2490	4732	01R-01J-02J
	LINKE	LINKE (6P) sx	-	-	2494	5521	01R-01J-02J
	MOIA	MCHGYPC (7+4+3) new		1AEBIBEF-1JLKAFBE	2495	5522	01R-01J-02J
	MOIA	MCHGYPC/C (6+4+3) new		3BACAF AE-3HKOF AEA	2497	5523	01R-01J-02J
	MOIA	MCHGYPC/CP01 (7+4+4)		8AEBIBFAE-8JLKAFBBA	2498	5522	01R-01J-02J
	MOIA	MCHGYPC/M (7+4+3) new		2AEBIBEF-2JLKAFBE	2496	5523	01R-01J-02J
	PIAGGIO	Porter (8P)		123	10030	5520	01V
	SPARK MINDA	TVS iQUBE	-	-	2489	5517	01R-19J-02J 01R-106-107
	THIRARD	Trafic 12 - 30 mm	-	-	2479	5510	01R-01J-02J
	UNION 	keyMASTER/ keyULTRA		123456789BCDE FGHJ	10029	3004	01V



FUTURA PRO NEWS WEB



MARCH 2024

1_2024 FUTURA PRO V.3.45.1



Fixed minor issues.

FEBRUARY 2024

1_2024 FUTURA PRO V.3.45.0



- Fixed an engraving issue.
- Fixed an issue with searching by Year.

NEW SYSTEMS

	LOCK MANUFACTURER	LOCK SYSTEM	PROFILE	SERIES	SN	DATA CARD	CLAMP
	ABUS	CSI-KB68 (2T-6W)	-	-	2465	5367	01R-01J-02J
	APECS	Apecs AP	-	-	2470	5492	01R-01J-02J
	AVOCET	ABS Pioneer		A00001-C14888	10025	5490	01V
	DOM 	DOM RS 7SI (Prf. 302) (6+5)	-	-	2473	5447	01R-166-167
	DOM 	DOM RS 7SI (Prf. 302) (6P)		01234567	10021	5443	11V
	DOM 	DOM RS 7SI (Prf. 303) (6+5)	-	-	2474	5448	01R-166-167
	DOM 	DOM RS 7SI (Prf. 303) (6P)		01234567	10022	5444	11V
	DOM 	DOM RS SIRIUS (Prf. 300-301) (6+5)	-	-	2472	5442	01R-166-167
	DOM 	DOM RS SIRIUS (Prf. 300-301) (6P)		01234567	10020	5438	11V
	dormakaba GEGE	PX-PXP (6P)		1234567890	10027	3706	01V
	DORSET	DORSET COMPUTER KEY	-	-	2464	5435	01R-01J-02J
	FF- FACCHINETTI 	Facchinetti C19		315700000024I- 39FJ6J6J6J6J6	2475	5503	01R-01J-02J



FUTURA PRO NEWS WEB



KELOP	K100		123456	10026	5500	01V
MLS MAUER	CY100 KT179 (6p)		000001-101092	2462	1851	01R-01J-02J
MLS MAUER	MLS Elite 1 KT179 (6p) - Red line		000001-101092	2461	1851	01R-01J-02J
MOIA	MCHGYPC/C/30+10	-	-	2463	5495	01R-01J-02J
PROMOTER	Promoter		12345	10023	5487	01V
SARGENT	DG2-DG3 (6P)		123456	10024	428	08V
SPARK	VIDA LH		5001-6174	9982	5393	01V
SPARK	VIDA LH		7001-8174	9983	5393	01V
TOK- WINKHAUS	Winkhaus OVSX (P6)		0123456789A	10007	5430	10V
TOK- WINKHAUS	Winkhaus OVSX (VS-Position 1-3)	-	-	2426	5428	01R-148-51J
TOK- WINKHAUS	Winkhaus OVSX (VS-Position 8)	-	-	2427	5429	01R-149-51J



FUTURA PRO NEWS WEB



NOVEMBER 2023

1_2023 FUTURA/FUTURA PRO V.3.44.0

NEW SYSTEMS

	LOCK MANUFACTURER	LOCK SYSTEM	PROFILE	SERIES	SN	DATA CARD	CLAMP
	ABUS	Abus A91 (5P)	AO.....	00001-30000	10011	4684	01V
	ALPHA	Renault Clio EMERGENZA	-	-	2418	5408	01R-01J-02J
	BKS	BKS Series 57 (Prf. KA-KB-KC-KD)	-	-	2422	5413	01R-150-151
	Dormakaba 	dormakaba Ace (K72)	-	-	1307	3341	01R-01J-02J
	FIAM	-		123456	10019	5484	01V
	GERDA	Vita		0123456789	10018	5482	01V
	HONDA	AMAZE	H...	H001-H999	2459	2354	01R-01J-02J 01R-106-107
	LINCE	Lince 7x7x6 (XL)	-	-	2454	5466	01R-01J-02J
	MCM	MCM BPS (6P)	0.....	162-17HH6	2447	3113	01R-01J-02J
	METAL	Metal 2x6J	-	-	2457	5469	01R-01J-02J
	METAL	Metal X6J	-	-	2456	5469	01R-01J-02J
	MOIA	MCHGYPC/C/30+10	-	-	2463	4172	01R-01J-02J
	PRORACK	-	...	001-100	10017	5473	01V
	PRORACK	HAVAL (2T-8W)	-	-	2460	5483	01R-19J-02J 01R-106-107
	SANDHAR	TVS APACHE RTR 220			2445	5445	01R-19J-02J 01R-03J-02J
	SILCA	5EY35P (6+6+6)	-	-	10013	5454	01V+B14
	SILCA	5EY35P (6+6+6)	-	-	10012	5453	01V+B14
	SILCA 	DIR5R	-	-	2458	5481	01R-01J-02J
	SUZUKI	-		1234	10016	5471	01V
	TriMark	TriMark (5P)		1001-1240	10014	5456	01V
	YALE	-		123	10015	5458	01V



FUTURA PRO NEWS WEB



	YALE	Yale 2000 Plus Series		ABC10001- ADB18058	1660	4050	01R-19J-02J
	ZEISS-IKON	Zeiss-Ikon Mirrored VRS		1234567890ABC DEFGHIL	10010	5452	01V+B18



FUTURA PRO NEWS WEB



AUGUST 2023

1_2023 FUTURA/FUTURA PRO V.3.43.0

NEW SYSTEMS

	LOCK MANUFACTURER	LOCK SYSTEM	PROFILE	SERIES	SN	DATA CARD	CLAMP
	ABUS 	Abus Vela 3000 - Xelus	-	-	2421	5403	01R-01J-02J
	ABUS-PFAFFENHAIN	Abus Z14 (3P)	-	-	2424	5415	01R-24J-25J
	ABUS-PFAFFENHAIN	Abus Z14 (4P)	-	-	2423	5414	01R-24J-25J
	AGB 	AGB GENIO		0123456789ABC DEFGH IJKLMNOPQRST UVWXYZ	2341	5220	01R-01J-02J
	AUSFILE	Ausfile PLAIN		123	9993	5411	01V
	EVVA 	Evva AKURA 44 Vario	-	-	2425	5427	01R-138-87J
	FF-FACCHINETTI 	Facchinetti C19		2370001-2411184	2416	5399	01R-01J-02J
	GERDA 	GERDA EXXO (5+5)(2T-5W)		1AK0001-9TK0504	2337	5219	01R-90J-02J
	GIVI	Givi (4+3)	-	-	2441	5436	01R-01J-15J
	HONDA	Honda Emergency Key (2T-6W)	-	-	2446	5446	01R-52J-53J
	ISEO 	ISEO CSF F90 SPI (9000D)	XGA.....	000001-012882	2444	5441	01R-147-51J
	ISEO 	ISEO CSF F90 SPI (9000N)	XGA.....	000001-012882	2443	5440	01R-147-51J
	ISEO 	Iseo RME Factory Cantiere/Padronale	NCB.....	000001-109903	2428	1597	01R-11J-02J
	ISEO 	R6 Plus SX2 Cantiere/Padronale	GFB.....	000001-112540	2431	5391	01R-01J-02J
	ISEO 	R6 Plus SX3 Cantiere/Padronale	GHB.....	000001-112540	2434	5391	01R-01J-02J
	ISEO 	R6 Plus SX4 Cantiere/Padronale	GLB.....	000001-112540	2437	5391	01R-01J-02J
	ISEO 	R6 Plus SX5 Cantiere/Padronale	GNB.....	000001-112540	2440	5391	01R-01J-02J
	ISEO 	R6 SPI SX2	GFC.....	000001-006056	2430	5391	01R-01J-02J
	ISEO 	R6 SPI SX3	GHC.....	000001-006056	2433	5391	01R-01J-02J
	ISEO 	R6 SPI SX4	GLC.....	000001-006056	2436	5391	01R-01J-02J



FUTURA PRO NEWS WEB



	ISEO	R6 SPI SX5	GNC.....	000001-006056	2439	5391	01R-01J-02J
	ISEO	R6 SX2	GFA.....	000001-039610	2429	5391	01R-01J-02J
	ISEO	R6 SX3	GHA.....	000001-039610	2432	5391	01R-01J-02J
	ISEO	R6 SX4	GLA.....	000001-039610	2435	5391	01R-01J-02J
	ISEO	R6 SX5	GNA.....	000001-039610	2438	5391	01R-01J-02J
	MERONI	-		1234	10000	5422	01V
	SANDLEFORD	-		123	10001	5423	01V



FUTURA PRO NEWS WEB



JUNE 2023

1_2023 FUTURA/FUTURA PRO V.3.42.0

NEW SYSTEMS

	LOCK MANUFACTURER	LOCK SYSTEM	PROFILE	SERIES	SN	DATA CARD	CLAMP
	ABUS	Oval Cyl DK		123456789	9986	5397	01V
	ABUS	Oval Cyl NO		12345678	9987	5398	01V
	ASSA ABLOY	412 (6P)		123456	9990	5381	01V
	ATRA	Power (4+6+6)	-	-	2420	5409	01R-11J-02J
	CVL	CVL2- CVL2R (system 5963)		005001-006872	9992	4771	01V
	dormakaba 	dormakaba Gemini II	-	-	1279	3241	01R-01J-02J
	GEVY	Gevy 5P		12345	9985	5396	01V
	GEVY	Gevy 6P		12345	9984	5396	01V
	ICSA	SGK Modello S2/S3	B.....	000002-107605	9991	5410	01V
	ISEO 	Iseo WS AP2R N	PSA.....	000001-031185	2316	5177	01R-01J-02J
	ISEO 	Iseo WS AP3R N	PTA.....	000001-187110	2318	5179	01R-01J-02J
	ISEO 	R6 SX1 Plus	GDB.....	000001-112540	2409	5391	01R-01J-02J
	ISEO 	R6 SX1 SKG	GDA.....	000001-039610	2408	5391	01R-01J-02J
	ISEO 	R6 SX1 SPI	GDC.....	000001-036610	2407	5391	01R-01J-02J
	ISEO 	R6 SX1 Standard	GDA.....	000001-039610	2406	5391	01R-01J-02J
	POTENT	Potent SY30- SY32- SY35- C11		2260001-2301184	2415	4360	01R-01J-02J
	PREFER	C2C (5+5)	TAA.....	800001-800720	2399	5208	01R-01J-02J
	PROLOX	Prolox 6P		12345678	9988	5400	01V
	SIKURO	SIKURO	-	-	2417	5402	01R-01J-02J
	SPARK	-		0001-1174	9994	5412	01V
	VACHETTE	VMI		1234567	9989	5404	01V



FUTURA PRO NEWS WEB



APRIL 2023

1_2023 FUTURA/FUTURA PRO V.3.41.0

NEW SYSTEMS

	LOCK MANUFACTURER	LOCK SYSTEM	PROFILE	SERIES	SN	DATA CARD	CLAMP
	ABUS 	Abus Integral Pro (Long Neck)	-	-	2382	5371	01R-143-144
	ABUS 	Abus Integral Pro (Short Neck)	-	-	2376	5350	01R-143-144
	CVL	CVL J6 (6+5)	AA....	1HD6-4XZ8	2405	4773	01R-01J-02J
	EBH AG	FORMAT		00001-30000	2410	5392	01R-05J-06J
	FAB NG 	FAB MKS		0369CFI	9981	5386	01V
	IFAM 	PLATINUM WX - IRIIDIUM WX		600003-708563	2396	5385	01R-05J-06J
	ISEO 	Iseo R700	DBC.....	000001-200000	2403	868	01R-01J-02J
	ISEO 	Iseo R700 Cantiere	DCA.....	000001-011890	2404	868	01R-01J-02J
	ISEO 	Iseo R700 S3	DFE.....	000001-030040	2398	868	01R-01J-02J
	LINCE 	Lince YX (C7X)	-	-	2394	5380	01R-24J-25J
	SALPIE	Salpie KFR	-	-	2412	5394	01R-01J-02J



FUTURA PRO NEWS WEB



JANUARY 2023

1_2023 FUTURA/FUTURA PRO V.3.40.0

NEW SYSTEMS

	LOCK MANUFACTURER	LOCK SYSTEM	PROFILE	SERIES	SN	DATA CARD	CLAMP
	ABUS	Abus D6 Basic	-	-	2391	3325	01R-05J-06J
	ABUS	Abus D66	-	-	2390	3325	01R-05J-06J
	ABUS	Abus D6PS CK	DC.....	00001-30000	2389	3325	01R-05J-06J
	ABUS	B5		12345	9976	3908	01V
	ASSA ABLOY	CY106 Sirio /153		000016-375006	2379	1851	01R-01J-02J
	ASSA ABLOY	Triton 2		111111-888888	9975	5352	02V
	ASSA ABLOY	Triton 2 (Side Code)	-	-	5353	5353	01R-68J-69J
	AXA	-		1115X-E9484	9978	1366	01V
	CL	CL4 (2T-6W)	-	-	2393	5384	01R-145-141
	DOM 	Dom HQ2	-	-	2388	5211	01R-88J-89J
	DOM 	Dom TwinTec (Prf. 327)	-	-	2384	5373	01R-88J-89J
	DOM 	Dom TwinTec (Prf.327;328;329;330)	-	-	2383	5372	01R-88J-89J
	DOM 	Dom TwinTec (Prf. 328)	-	-	2385	5374	01R-88J-89J
	DOM 	Dom TwinTec (Prf. 329)	-	-	2386	5375	01R-88J-89J
	DOM 	Dom TwinTec (Prf. 330)	-	-	2387	5376	01R-88J-89J
	GERDA	Contra 900/8W (2T-6W)	-	-	2378	5367	01R-01J-02J
	GERDA	Flex 1200/12V (2T-4W)	-	-	2377	5359	01R-01J-02J
	ISEO 	CSF F90 SPI BSI	XGB.....	000001-119136	9974	5163	01V
	ISEO 	CSR R90 Factory	PHG.....	000001-129660	2380	5368	01R-11J-02J
	LINCE 	Lince Y (C7)	-	-	2381	5369	01R-11J-02J
	WURTH	W30	RW.....	00001-30000	9979	5383	01V
	WURTH	W6X	WX.....	00001-30000	2392	5382	01R-05J-06J

OCTOBER 2022

1_2022 FUTURA/FUTURA PRO V.3.39.0



 Solved a problem related to importing user tables .

NEW SYSTEMS

	LOCK MANUFACTURER	LOCK SYSTEM	PROFILE	SERIES	SN	DATA CARD	CLAMP
	ABUS	6S Snake (2T-6W)		00001-01315	2369	5331	01R-01J-02J
	ABUS	C42TI, C50TI, C51TI, TI11 (3P)	...	001-232	9967	5333	01V
	ABUS	C42TI, C50TI, C51TI, TI11 (4P)		0001-1356	9966	5333	01V
	ABUS 	Magtec 1500	-	-	9961	5327	01V
	ABUS 	Magtec 2500	-	-	9960	5326	01V
	ABUS 	Magtec.2500 (1 dimple row)	-	-	2368	5324	01R-01J-02J
	ABUS 	Magtec.2500 (2 dimple rows)	-	-	2367	5322	01R-01J-02J
	ABUS 	Magtec.2500 (3 dimple rows)	-	-	2366	5318	01R-01J-02J
	ABUS	RH6 (74 series)		123456	9965	5332	01V
	AKM 	TT2190_AV3001M2R		12345	9963	5330	01V
	BMB	-	B...	601-800	9964	2376	01V
	CL	CL (5+5+3)	-	-	2375	5348	01R-01J-02J
	CORBIN	Corbin Pyramid (7P)		0123456789	9957	5319	01V
	GERDA	Flex 1000/10K		123	9959	5325	01V
	GERDA	Flex 1200/10S		12345	9958	5317	01V
	HUF	Land Rover (2T-7W)	-	-	2371	5341	01R-19J-02J 01R-03J-02J
	MG (MONTI) 	HSP2 (left profile)	-	-	2373	5342	01R-42J-43J



FUTURA PRO NEWS WEB



MG (MONTI) 	HSP2 (right profile)	-	-	2374	5343	01R-42J-43J
MLS-MAUER 	Elit 2/Elite 2 Red Line_KT178 (6+5)		000001-105560	2372	2242	01R-01J-02J
SANDHAR	Royal Enfield (2T-7W)	-	-	2370	5344	01R-19J-02J 01R-01J-02J+A34 01R-03J-02J
SANDHAR	Suzuki Access (6P)		1234	9956	5316	01V
SANDHAR	TVS (7P)		123	9962	5328	01V
UNION	UNION R101 (6P)		033330-199974	9973	5146	01V
YALE	YALE 600 KM R2		033330-199974	9971	5146	01V
YALE	YALE 600 R103		033330-199974	9972	5146	01V



FUTURA PRO NEWS WEB



SEPTEMBER 2022

1_2022 FUTURA/FUTURA PRO V.3.38.0



Status of the connection with MYKEYS Pro in the "Diagnostics-Connections" menu.

NEW SYSTEMS

	LOCK MANUFACTURER	LOCK SYSTEM	PROFILE	SERIES	SN	DATA CARD	CLAMP
	ASEC	Caveo	-	-	2364	5314	01R-01J-02J
	ASSA ABLOY 	CYS10/C250/Comfort (+) NG - KD/KA		02468ACEGI	9953	5312	01V
	ASSA ABLOY 	CYS10/C250/JPM_Ark oZ/Comfort (+) NG – MKS		0123456789ABC DEFGHI	9954	5313	01V
	B-HARKO	H6 (6P)		12345678	9951	5298	01V
	CHERY	E3 (2T-8W)	-	-	2356	5299	01R-01J-02J 01R-106-108
	CL	-	-	-	9952	5301	01V
	CORBIN	Access 3 AP (6P)		0123456	9945	5289	01V
	CORBIN	Corbin 852 (6P)		B0123456	9941	5285	01V
	CORBIN	Corbin 981 (6P)		B0123456789	9943	5286	01V
	CORBIN	Corbin 981 (7P)		B0123456789	9942	5286	01V
	CORBIN	DH Class (Pre SYS 70) (6P)		0123456789	9935	5282	01V
	CORBIN	DH Class (Pre SYS 70) (7P)		0123456789	9934	5282	01V
	CORBIN	N Class (Pre SYS 70) (5P)		0123456789	9938	5283	01V
	CORBIN	N Class (Pre SYS 70) (6P)		0123456789	9937	5283	01V
	CORBIN	N Class (Pre SYS 70) (7P)		0123456789	9936	5283	01V
	CORBIN	N Class (SYS 70) (6P)		123456	9940	5284	01V
	CORBIN	N Class (SYS 70) (7P)		123456	9939	5284	01V



FUTURA PRO NEWS WEB



	CORBIN	Z Class (Pre SYS 70) (7P)		0123456789	9933	5281	01V
	DAF	Daf (6P)	-	-	2352	5288	01R-01J-02J
	HAIMA	M3 (2T-8W)	-	-	2360	5303	01R-01J-02J 01R-106-107
	IFAM	Ifam PLATINUM M - IRIDIUM M		30001-196656	2365	2772	01R-01J-02J
	JINBEI	Jinbei 750 (2T-8W)	-	-	2362	5309	01R-01J-02J 01R-106-107
	MINDA	Jawa Perak (7P)		2001-3170	9946	5295	01V
	MWT	MWT (6P)	-	-	2357	5300	01R-01J-02J
	MWT	MWT (7P)	-	-	2358	5300	01R-01J-02J
	QUNSHEN	Qunshen (8+6)	-	-	2353	5290	01R-01J-02J
	SANDHAR	TVS (6P)		1234	9955	5315	01V
	SECUREMME	EVOK1 MASTER (6P)	-	-	2361	4660	01R-01J-02J
	UAP	K4 Horizontal	-	-	2363	5311	01R-01J-02J



FUTURA PRO NEWS WEB



JUNE 2022

1_2022 FUTURA/FUTURA PRO V.3.37.0

NEW SYSTEMS

	LOCK MANUFACTURER	LOCK SYSTEM	PROFILE	SERIES	SN	DATA CARD	CLAMP
	ABUS	Oval Cyl SWE	SW.....	SW000001- SW130000	9929	355	01V
	AGB 	AGB GENIO		0123456789ABC DEFGH IJKLMNOPQRST UVWXYZ	2341	5220	01R-01J-02J
	ALPHA 	Aston Martin AM800 (2T-4W)		1-2000	2348	5248	01R-139-02J
	ALPHA 	Renault BJA-HJB (2T-7W)		1-2000	2349	5271	01R-139-02J
	ASSA	SIRIO KT161		000011-375302	2350	1851	01R-01J-02J
	BKS	BKS WS50 (Profile RC)	-	-	2342	5222	01R-140-38J
	FAB 	Aston Martin AM500 (2T-4W)		1-2224	2347	5229	01R-139-02J
	GERDA	GERDA EXXO (5+5) (2T-5W)	-	-	2337	5219	01R-90J-02J
	ISEO 	Iseo R500 SPI	TEC.....	000001-162096	2338	1597	01R-11J-02J
	ISEO 	Iseo R500 SPI Cantiere	TGA.....	000001-026424	2339	1597	01R-11J-02J
	ISEO 	Iseo R500 SPI Padronale	TGA.....	100001-126424	2340	1597	01R-11J-02J
	LOB	DRAGON-LOBIX (6P)		0123456789	9931	5223	01V
	MAZDA	-		1234	9932	5276	01V
	MILLERS	Millers (7P)		1234567	9930	5221	01V
	MOTTURA	3DKey	-	-	2335	5218	08R



FUTURA PRO NEWS WEB




MAY 2022

1_2022 FUTURA/FUTURA PRO V.3.36.0



- New function COPY by ORIGINAL for FUTURA AUTO model: this function lets the user to copy a car key by original using a mechanical tracer to read the cuts.

This process works well for flat car keys only.



Attention: please, to avoid breaking the mechanical tracer, do not use it to read plastic or aluminum keys



- Fixed a bug in the EVVA 4KS card



FUTURA PRO NEWS WEB



APRIL 2022

1_2022 FUTURA/FUTURA PRO V.3.35.1



■ Fixed a bug in the Engraving editor

APRIL 2022

1_2022 FUTURA/FUTURA PRO V.3.35.0

	FUTURA AUTO: now is possible to modify the keyblank dimension before copying the key
	Solved the issue for registering the FUTURA machine in MYKEYSPRO using the Futura Android App of the tablet. In the SSI queue, loading an XML KESO MKS, the name of the key will be shown. Small adjustments have been done cutting ABUS BRAVUS PRO (all variants) key system according to ABUS notice.

NEW SYSTEMS

	LOCK MANUFACTURER	LOCK SYSTEM	PROFILE	SERIES	SN	DATA CARD	CLAMP
	ASSA ABLOY	ASS196R (5+5+5)	-	-	2313	5172	01R-11J-02J
	ELZETT	Elzett 758		012345678	9926	5215	01V
	EURO LOCKS	Euro Locks U new (2T - 5W)	-	-	2329	5213	01R-01J-02J
	ISEO 	Iseo RME Factory	NAC.....	000001-017163	2330	1597	01R-11J-02J
	ISEO 	Iseo RME KS1	NKS.....	000001-017163	2331	1597	01R-11J-02J
	ISEO 	Iseo RME KS2	NDA.....	000001-017163	2332	1597	01R-11J-02J
	ISEO 	Iseo R6 SPI	ASP.....	000001-004044	2333	869	01R-01J-02J
	ISEO 	Iseo R500	TEB.....	000001-056616	2334	1597	01R-11J-02J
	KIA	Kia (2T-- 8W)	KB....	0001-3000	2324	4129	01R-01J-02J
	KIA	Kia (2T-- 8W)	KC....	0001-2900	2325	4129	01R-01J-02J
	KIA	Hyundai (2T-- 8W)	HD....	0001-2500	2326	4129	01R-01J-02J
	KIA	Hyundai (2T-- 8W)	HG....	0001-3000	2327	4129	01R-01J-02J
	KIA	Hyundai (2T-- 8W)	X....	0001-3000	2328	4129	01R-01J-02J
	MAUER 	CY100 (6P)		000016-375006	2336	1851	01R-11J-02J



FUTURA PRO NEWS WEB



	MINDA	-		5001-7999	9924	3866	01V
	MINDA	-		5001-5999	9925	3866	01V
	MINDA	-	A0...	001-700	9927	5216	01V
	MINDA	-	R0....	1001-2000	9928	5217	01V



FUTURA PRO NEWS WEB



MARCH 2022

1_2022 FUTURA/FUTURA PRO V.3.34.2



- FUTURA EDGE PLUS: jaw calibration routine has been improved.
- Optical reader: the calibration parameter C2 is now visible

FEBRUARY 2022

1_2022 FUTURA/FUTURA PRO V.3.34.1



- Only for **FUTURA** model
A bug in the setting of cutting speed of flat keys has been fixed.



FUTURA PRO NEWS WEB



JANUARY 2022

1_2022 FUTURA/FUTURA PRO V.3.34.0

NEW SYSTEMS

	LOCK MANUFACTURER	LOCK SYSTEM	PROFILE	SERIES	SN	DATA CARD	CLAMP
	ASSA ABLOY	ASSA ABLOY Gemma		033330-199974	9894	5146	01V
	BKS	BKS Serie 36 (6P)		0123456789AB	9922	5004	01V
	BORG LOCKS	Borg locks 1700-YS (2T-4W)	-	-	2312	5165	01R-01J-02J
	EUROSECURE	Euro Secure ES n. 3 (6P)		123456789	9918	5167	01V
	EVVA 	AKURA 44 Distributors (6+5+5)	-	-	2314	5174	01R-138-87J
	EVVA 	AKURA 44 Individual (6P)	-	-	2311	5166	01R-138-87J
	FAB	FAB R104		033330-199974	9895	5146	01V
	FAB	FAB R5		L00002-LA6334	9890	5145	01V
	FAB NG	FAB 2 Profi ** (5 pins)		0123456789ABC DEFGHI	9910	5068	01V
	FAB NG	FAB 3 Profi *** (6 pins)		0123456789ABC DEFGHI	9912	5161	01V
	FAB NG	FAB 3*** (5 pins)		0123456789ABC DEFGHI	9911	5068	01V
	FAB NG	FAB 4 **** (6 pins)		0123456789ABC DEFGHI	9916	5161	01V
	GERA 	GERA 3000 PLUS SPI	XZA0.....	00001-09746	9915	5164	01V
	GERA 	GERA 3000 SPI	XYA0.....	00001-09746	9917	5164	01V
	ISEO 	CSF F9 SPI	XEA0.....	00001-12882	9913	5163	01V
	ISEO 	CSF F90 SPI	XGA0.....	00001-12882	9914	5163	01V
	KIA	KIA (2T - 8W)	MQ....	0001-2500	2320	4362	01R-01J-02J
	KIA	KIA (2T-7W)	CV....	3001-5409	2319	5096	01R-01J-02J
	LORI	Lori 80 Keyway		123456789	9919	5173	01V
	LORI	Lori 90 Keyway		1234567	9920	5175	01V
	STAR	Star S100TM (5P)		012345678	9487	606	01V



FUTURA PRO NEWS WEB



	UNION	UNION R101		L00002-LA6334	9891	5145	01V
	VACHETTE	VACHETTE R1		L00002-LA6334	9893	5145	01V
	VBH	VBH Q (6P+2T-5W)	-	-	2321	5181	01R-01J-02J
	YALE	YALE 500+ Upgrade R2		L00002-LA6334	9892	5145	01V



FUTURA PRO NEWS WEB



DECEMBER 2021

1_2021 FUTURA/FUTURA PRO V.3.33.1



- Only for **FUTURA AUTO** model: new “Cutting speed variation” function in card copy for flat and laser keys. This function allows the user to change the speed of advancement and the amount of material to be removed at each pass based on the type of material and the thickness of the key to be encrypted.



- Fixed some minor bugs (Cards: 4357 Wilka Carat S1-S4; 2502 Abus).

DECEMBER 2021

1_2021 FUTURA/FUTURA PRO V.3.33.0



- New function to monitor cutter wear with notifications and emails .

NOVEMBER 2021

1_2021 FUTURA/FUTURA PRO V.3.32.1



Fixed a severe bug on Tethering connection.

NOVEMBER 2021

1_2021 FUTURA/FUTURA PRO V.3.32.0



The procedure used to connect the tablet to the machine both directly and through a Wi-Fi network has been improved.



Problem solved regarding decoding with cutter card 3840.
Problem solved regarding decoding ABUS Bravus 2000 key.

NEW SYSTEMS

	LOCK MANUFACTURER	LOCK SYSTEM	PROFILE	SERIES	SN	DATA CARD	CLAMP
	ASSA	SIRIO KT130		000016-857986	2302	1851	01R-01J-02J
	ASSA	SIRIO PRO KT150 - Red Elite		000001-059000	2303	2242	01R-01J-02J
	CES 	CES WNP (5+5+6)	-	-	2289	5123	01R-01J-02J
	EBERHARD	EBERHARD (5P)	H...	H700-H760	9883	5120	01V
	GREENTEQ	ORION 3 Star	-	-	2307	5141	01R-01J-02J
	HARLEY DAVIDSON	HY10R (5P)	...	001-200	9884	5121	01V
	ISEO 	ISEO R50 Extra (Cantiere)	SME.....	000001-029315	2304	1597	01R-11J-02J
	ISEO 	ISEO R50 Extra (Padronale)	SME.....	100001-129315	2305	1597	01R-11J-02J
	JAY SWITCH			123	9889	5138	01V
	LDV	LDV TOY40 (2T-4W)	-	-	2306	5134	01R-01J-02J
	MCM	MCM BPSX (6+6)	-	-	2296	5133	01R-01J-02J



FUTURA PRO NEWS WEB



	MCM	MCM SCX NEW (6+5)	-	-	2295	5132	01R-01J-02J
	Meesenburg Großhandel KG	Blaugelb Profilzylinder 6S		1234567	9885	5125	01V
	Meesenburg Großhandel KG	Blaugelb Wendeschlüssel (6P)	BG.....	00001-30000	2301	5140	01R-05J-06J
	MINDA			9001-9999	9886	5135	01V
	SANDHAR			123	9887	5137	01V
	SANDHAR			123	9888	5138	01V
	SIKURO	SIKURO (6P)	-	-	2288	5122	01R-137-02J
	STAR	STAR S100TM (4+4)	-	-	2141	4704	01R-01J-02J
	THIRARD	THIRARD TIGER 6	-	-	2293	5128	01R-01J-02J
	THIRARD	THIRARD TRAFIC 12	-	-	2292	5127	01R-01J-02J
	THIRARD	THIRARD TRANSIT 1	-	-	2294	5129	01R-01J-02J
	VIRO	VIRO EUROMONOLITH (6P)	ED-K-A....	0001-6679	2300	1604	01R-01J-02J
	VIRO	VIRO EURO-PRO (5P)	EPL-B....	3259-5980	2298	1604	01R-01J-02J
	VIRO	VIRO EURO-PRO (6P)	EPL-A....	07222-13900	2299	1604	01R-01J-02J
	WANGTONG	WANGTONG (6P)	...	001-200	9882	5119	01V



FUTURA PRO NEWS WEB



OCTOBER 2021

1_2021 FUTURA/FUTURA PRO V.3.31.1



■ Solved a minor Software problem on HONDA card 1587 and 2354



FUTURA PRO NEWS WEB



JULY 2021

1_2021 FUTURA/FUTURA PRO V.3.31.0

NEW SYSTEMS

	LOCK MANUFACTURER	LOCK SYSTEM	PROFILE	SERIES	SN	DATA CARD	CLAMP
	ABUS	ABUS E200		EB000001- EB30000	9873	5100	01V
	ABUS	ABUS E300	EC.....	EC00001- EC30000	2251	5099	01R-05J-06J
	ABUS 	ABUS EC880		NH100001- NH131841	2280	5102	01R-01J-02J
	AMIG 	AMIG 20000 (6P+4W)		V0100001- V2059460	2219	4945	01R-01J-02J
	AMIG 	AMIG 10000 (6P)		B0000001- S0012620	2217	4947	01R-01J-02J
	AMIG 	AMIG 10000E (6P)		P0000001- Z0012620	2218	4948	01R-01J-02J
	AMIG 	AMIG 20000 (6P)		V0100001- V2059460	2283	5111	01R-01J-02J
	AVOCET	Avocet ABS Master RH	-	-	2282	5110	01R-01J-02J
	BATON	Baton UNITE SERIE 5600	-	-	2284	5112	01R-01J-02J
	GERDA	Gerda Hplus (6 pin)	-	-	2281	5109	01R-01J-02J
	LINCE	LINCE C6XL	-	-	2285	5113	01R-01J-02J



FUTURA PRO NEWS WEB



JULY 2021

1_2021 FUTURA/FUTURA PRO V.3.30.2



- The MyKeys Safe function has been upgraded. Please contact your local Dealer for more information.



FUTURA PRO NEWS WEB



JUNE 2021

1_2021 FUTURA/FUTURA PRO V.3.30.0

NEW SYSTEMS

	LOCK MANUFACTURER	LOCK SYSTEM	PROFILE	SERIES	SN	DATA CARD	CLAMP
	BASI	BASI V50		-	9880	5092	01V
	BASI	BASI V55	-	-	2273	5089	01R-01J-02J
	CARRYBOY	CRY2 (2T-7W)	-	-	2252	5035	01R-131-132
	CARRYBOY	CRY2 (2T-7W)	-	-	2279	5098	01R-131-132
	CISA 	ASIX P8	P8	XN.0352.10	2244	1414	01R-05J-06J
	CISA 	ASIX P8 CA	P8 CA	XN.0358.10	2245	1414	01R-05J-06J
	CISA 	ASIX P8 CE	P8 CE	XN.0362.10	2246	1414	01R-05J-06J
	DELTA	DELTA GB5	-	-	2253	5041	01R-01J-02J
	DIERRE 	Dierre D-UP		0000001-0943516	2271	5088	01R-01J-02J
	DIERRE 	Dierre D-UP		0000001-0235920	2272	5088	01R-01J-02J
	EUROSECURE	Euro Secure (6P)		123456789	5129	5093	01V
	GUARD	GUARD G100		00001-99999	2276	5095	01R-01J-02J
	HUF	Huf-Mahindra (2T-9W)	-	-	2255	5046	01R-19J-02J
	HYUNDAI	Hyundai Smart Key (2T-7W)	S....	3001-5409	2277	5096	01R-01J-02J
	IBFM	IBFM 9993	-	-	2278	5097	01R-01J-02J
	KENSTAN	Kenstan (8P)		1234567	757	2258	02R
	MAZDA	7th Generation		12345	9879	5091	01V
	PHILLIPS	Phillips 4200 (6P)	-	-	2275	5094	01R-01J-02J
	SOPRANO	Cilindro Clasico	-	-	2274	5090	01R-01J-02J
	TARONI	TAR15 (5+4) NEXT	-	-	2262	5083	01R-01J-02J
	TARONI	TAR15 (6P) NEXT	-	-	2265	5084	01R-01J-02J



FUTURA PRO NEWS WEB



TARONI	TAR15R (5+4) NEXT	-	-	2263	5082	01R-01J-02J
TARONI	TAR15R (6P) NEXT	-	-	2268	5085	01R-01J-02J
TARONI	TAR16 (6+5) NEXT	-	-	2269	5086	01R-01J-02J
TARONI	TAR16 (6P) NEXT	-	-	2264	5084	01R-01J-02J
TARONI	TAR16R (6+5) NEXT	-	-	2270	5087	01R-01J-02J
TARONI	TAR16R (6P) NEXT	-	-	2266	5085	01R-01J-02J
TARONI	TAR17 TAR17R (3P) NEXT	...	-	9876	5080	01V
TARONI	TAR17 TAR17R (3P) NEXT	...	-	9876	5080	01V
TARONI	TAR25 TAR25R (6P) NEXT		-	9877	5078	01V
TARONI	TAR25 TAR25R (6P) NEXT		-	9877	5078	01V
TARONI	TAR5 TAR5R (5P) NEXT		-	9878	5081	01V
TARONI	TAR5 TAR5R (5P) NEXT		-	9878	5081	01V



FUTURA PRO NEWS WEB



March 2021

1_2021 FUTURA V.3.22.0 – FUTURA PRO V.3.24.0

NEW SYSTEMS

	LOCK MANUFACTURER	LOCK SYSTEM	PROFILE	SERIES	SN	DATA CARD	CLAMP
	ABUS	ABUS E200		EB000001- EB30000	9873	4684	01V
	ABUS	ABUS E300	EC.....	EC00001- EC30000	2251	3325	01R-05J-06J
	ASSA	ASSA IKON VRS (6P)		1234567890ABC DEFGHIL	9555	4974	01V-B17
	CISA 	ASIX P8	-	-	2244	1414	01R-05J-06J
	CISA 	ASIX P8 CA	-	-	2245	1414	01R-05J-06J
	CISA 	ASIX P8 CE	-	-	2246	1414	01R-05J-06J
	ISEO 	ISEO R6 Plus (no chiave di cantiere)	AMP.....	000001-028834	2228	869	01R-01J-02J
	ISEO 	ISEO F7 (6P)		000001-010751	9554	4944	01V
	KESO 	Keso K6000FP2 Syst. 10 /Var. 45	-	-	2230	4976	01R-01J-02J
	MCM	EA (5P)		1234567	9872	4399	01V
	MOJA	MOJA Serie J	-	-	2250	5037	01R-01J-02J
	Mul-T-Lock 	Mul-T-Lock 3DS Break Secure		000001-059000	2109	2242	01R-01J-02J
	WINKHAUS 	WINKHAUS ON-tra + (EGS)	-	-	2247	5032	01R-78J-79J
	WINKHAUS 	WINKHAUS ON-tra + (P1)	-	-	2248	5033	01R-78J-79J
	WINKHAUS 	WINKHAUS ON-tra + (P3)	-	-	2249	5034	01R-78J-79J
	YALE	YALE Y2P		C30001-C51204	2227	4970	01R-01J-02J
	YALE	YALE Y2S		30001-62163	2229	4973	01R-01J-02J

December 2020

1_2020 FUTURA V.3.21.0 – FUTURA PRO V.3.23.0



■ Solved a minor Software problem (card 477)

NEW SYSTEMS

	LOCK MANUFACTURER	LOCK SYSTEM	PROFILE	SERIES	SN	DATA CARD	CLAMP
	ABUS 	Vela Pro 3000	-	-	2216	4946	01R-01J-02J
	AMIG	AMIG 20000 (6P+4W)	-	-	2219	4945	01R-01J-02J
	AMIG	AMIG 10000 (6P)	-	-	2217	4947	01R-01J-02J
	AMIG	AMIG 10000E (6P)	-	-	2218	4948	01R-01J-02J
	CISA 	Serial Z75	(XN003210)	1-84006AH	2220	2637	01R-05J-06J
	ERA			1234567	9861	4965	01V
	EUROSPEC	MPX6 3 STAR		123456789	9862	4966	01V
	FEDERAL	APE BS3		WA400001- WE411502	2223	4963	01R-01J-02J
	GEGE	p Extra - pExtra plus 6 pins		1234567890	9859	4962	01V
	ISEO 	ISEO R50 A2P	SFC.....	000001-107185	2214	1597	01R-11J-02J
	ISEO 	ISEO R7 A2P	EBA.....	000001-157864	2212	868	01R-01J-02J
	MAHINDRA			1234	9863	4967	01V
	MIWA	MIWA PS	-	-	2224	4960	01R-05J-02J
	MIWA	MIWA PR	-	-	2225	4961	01R-05J-02J
	NEXO N05	6SAB (6P)	-	-	2211	4936	01R-01J-02J
	NEXO N05	6S (6P)	-	-	2110	4935	01R-01J-02J
	OMEC	OMEC 2020/08	-	-	2226	4968	01R-05J-06J
	SILCA	SK3 MKS	-	-	2213	4941	01R-07J-08J



FUTURA PRO NEWS WEB



	SISO	SISO (2T-5W)	-	-	2222	4959	01R-129J-130J
	TATA	TATA NEXON	-	-	2221	4958	01R-19J-02J
	TATA	TIAGO (2T-8W)		3000-7559	2215	4942	01R-01J-02J
	WT	WT CAM LOCK		123456	9556	4952	01V
	YALE	Linus Adjustable Cylinder (6P)	P.....	P00001-P30614	9860	4964	01V



FUTURA PRO NEWS WEB



September 2020

1_2020 FUTURA V.3.20.1 – FUTURA PRO V.3.22.1



■ Solved a minor Software problem

September 2020 1_2020 FUTURA V.3.20.0 – FUTURA PRO V.3.22.0

NEW SYSTEMS

	LOCK MANUFACTURER	LOCK SYSTEM	PROFILE	SERIES	SN	DATA CARD	CLAMP
	ABUS 	ABUS X60	FS.....	00001-98246	9541	4776	01V
	ABUS 	Bravus 1500 (Shoulder stop)	-	-	2193	3655	01R-29J-30J
	ABUS 	Bravus 1500 (Tip stop)	-	-	2187	4010	01R-29J-30J
	ABUS 	Bravus 2500 (Shoulder stop)	-	-	2194	3656	01R-29J-30J
	ABUS 	Bravus 2500 (Tip stop)	-	-	2185	4023	01R-29J-30J
	ABUS 	Bravus 3500 (Shoulder stop)	-	-	2195	3657	01R-29J-30J
	ABUS 	Bravus 3500 (Tip stop)	-	-	2180	3832	01R-29J-30J
	ABUS 	Bravus Pro 1500 (Shoulder stop)	-	-	2190	4325	01R-29J-30J
	ABUS 	Bravus Pro 1500 (Tip stop)	-	-	2186	4322	01R-29J-30J
	ABUS 	Bravus Pro 2500 (Shoulder stop)	-	-	2191	4327	01R-29J-30J
	ABUS 	Bravus Pro 2500 (Tip stop)	-	-	2181	4323	01R-29J-30J
	ABUS 	Bravus Pro 3500 (Shoulder stop)	-	-	2192	4326	01R-29J-30J
	ABUS 	Bravus Pro 3500 (Tip stop)	-	-	2188	4321	01R-29J-30J
	ABUS 	Mintus	-	-	2189	4023	01R-29J-30J
	ABUS 	X12R (6+5)		X1R00001- X1R12952	2062	4525	01R-01J-02J
	ALBA	FM	-	-	2172	4777	01R-01J-02J
	ASSA ABLOY	Baodean MOD. 12	-	-	2171	4775	01R-01J-02J
	BRISANT	Ultion WXM (6P)	-	-	2168	4757	01R-128-02J
	BTV 	Snake (5+5)+(2T-4W)		AA00001- AA29688	2199	4918	01R-01J-02J
	BTV 	Snake (5+5)+(2T-4W)		AB00001- AB29688	2200	4918	01R-01J-02J
	BTV 	Snake (5+5)+(2T-4W)		BY00001- BY29688	2201	4918	01R-01J-02J



FUTURA PRO NEWS WEB



	BTV	Snake (5+5)+(2T-4W)		CA00001- CA29688	2202	4918	01R-01J-02J
	CHINA	SERRUPRIX (6P)	-	-	2183	4750	01R-01J-02J
	GREATWALL	Great Wall (4T-6W)	-	-	2198	2354	01R-01J-02J
	ISEO	Iseo F90 CSF	FA.....	000001-196122	9540	2504	01V
	LOCKMAN	MEGA CROSS (4.0)	-	-	1163	3031	01R-124-125
	NEXO 05	NEXO 05 (5 Pin)		123456789	9547	4917	01V
	SECUREMME	EVOK50 (6+5)	-	-	2166	4747	01R-126-127
	SECUREMME	EVOK75 (5+5)	-	-	2182	4784	01R-126-127
	STANDERS	CS115 (6P)	-	-	2196	4783	01R-05J-06J
	STS	IPS (6P)		0123456789	9544	4782	01V
	TARONI	TAR16 6 pin	-	-	2910	4780	01R-01J-02J
	TARONI	TAR16R 6 pin	-	-	2908	4779	01R-01J-02J
	TARONI	TAR27P (SERIE5) (6P)		B001001- B024117	9010	4500	01V
	TARONI	TAR27P (SERIE5) (6P)		C001001- C024117	9520	4500	01V
	TARONI	TAR27P (SERIE5) (6P)		D001001- D024117	9521	4500	01V
	TARONI	TAR27P (SERIE5) (6P)		E001001- E024117	9522	4500	01V
	TARONI	TAR27P (SERIE5) (6P)		F001001- F024117	9523	4500	01V
	TARONI	TAR27P (SERIE5) (6P)		K001001- K024117	9524	4500	01V
	XIAOHULU	NR.4	-	-	2184	4816	01R-01J-02J



FUTURA PRO NEWS WEB



May 2020

1_2020 FUTURA V.3.19.0 – FUTURA PRO V.3.21.0

NEW SYSTEMS

	LOCK MANUFACTURER	LOCK SYSTEM	PROFILE	SERIES	SN	DATA CARD	CLAMP
	ABUS 	ABUS G5X		GX00001A-GX30000A	2160	4744	01R-05J-06J
	ABUS 	ABUS D20 (6+7)		1-39610	1343	3433	01R-72J-73J
	ANBO	ANBO X1 (6 pin)	-	-	2158	4743	01R-01J-02J
	ASHICO	ASHICO (6 pin)	-	-	2165	4753	01R-01J-02J
	CARRYBOY	Carryboy (4T-6W)	-	-	2156	4738	01R-01J-02J-A34
	EVERLEO	EVERLEO (6+6)	-	-	2162	4751	01R-01J-02J
	GEVY	GEVY (5+4 pin)	-	-	2161	4746	01R-01J-02J
	HYUNDAI	Hyundai (2T-8W)	CK....	0001-2500	4732	2164	01R-01J-02J
	ISEO 	F7 KD	-	-	9526	4628	01V
	ISEO 	F7 MK Multiprofilo	-	-	9527	4626	01V
	LINKE	LINKE (6 pin)	-	-	2163	4752	01R-01J-02J
	LOCKMAN 	MEGA CROSS (2,9) (S)	-	-	1162	3030	01R-124-125
	PANPAN BUYANG	PANPAN BUYANG OML	-	-	2157	4742	01R-01J-02J
	SECUREMME 	EVOK50 (6+4)	-	-	2148	4747	01R-126-127
	SILCA	SK3 (1T)	-	-	1594	3905	01R-07J-08J
	VIRO	Serie 1030 Zama		1234567	9525	4745	01V



FUTURA PRO NEWS WEB



December 2019

1_2019 FUTURA V.3.18.0 – FUTURA PRO V.3.20.0

NEW SYSTEMS

	LOCK MANUFACTURER	LOCK SYSTEM	PROFILE	SERIES	SN	DATA CARD	CLAMP
	APECS	Apecs New Diamond (5P-4W)	-	-	2036	4501	01R-01J-02J
	BYD			1234567	9515	4721	01V
	BYD			12345678	9517	4728	01V
	CES 	CES RBM (5 pin)	-	-	2108	4631	01R-118-119
	CES 	CES RHM (5 pin)	-	-	2107	4627	01R-118-119
	CES 	CES RHM (6 pin)	-	-	2103	4624	01R-118-119
	CHERY			1234567890	9486	4701	01V
	CHERY			12345678	9508	4710	01V
	CHERY			12345	8766	3323	01V
	GEELY			12345678	9516	4722	01V
	GERDA	WK E1		1234567890	9507	4709	01V
	GREATWALL			1234567	9509	4711	01V
	HALKE			012345679	9518	4426	01V
	HYUNDAI	Hyundai (2T- 8W)	S....	0001-2500	2037	4732	01R-01J-02J
	HYUNDAI	Hyundai (2T- 8W)	Z....	0001-2501	2149	4732	01R-01J-02J
	IFAM	IFAM NK1000		N07507-N19818	2155	4733	01R-01J-02J
	KAKEN	Kaken NEW KXR- ED4N (2T-4W-5P)	-	-	2154	4731	01R-01J-02J
	LIPS			123456789	9519	816	01V
	LUFENG			12345678	9513	4719	01V
	M&C 	M&C Move (Main pins)		M011A0001- M106M3600	2143	4715	01R-95J-96J
	M&C 	M&C Move (Side)		M011A0001- M106M3601	2144	4716	01R-01J-02J



FUTURA PRO NEWS WEB



	M&C	M&C Move (Snake)		M011A0001- M106M3602	2145	4718	01R-14J-60J
	MAZDA			12345678	9511	4714	01V
	MEGA	Mega MEG2 (6P)		123456789	9506	4708	01V
	MOTTURA	Mottura CP6	-	-	2147	4729	01R-01J-02J
	SARGENT	DG1		0123456	9104	3890	01V
	TITAN	(K58 & T60)		123456789	8888	2201	01V
	WULING			123456	9510	4713	01V
	WULING			1234	9512	4717	01V



FUTURA PRO NEWS WEB



October 2019

1_2019 FUTURA V.3.17.0 – FUTURA PRO V.3.19.0

NEW SYSTEMS

	LOCK MANUFACTURER	LOCK SYSTEM	PROFILE	SERIES	SN	DATA CARD	CLAMP
	ADAPTA	PRIME HS	-	-	2140	4702	01R-01J-02J
	ASEC-SECURITY	VITAL (6P)		01234567	9485	4699	01V
	AVOCET 	ABS Master	-	MG3001178-MG8999932	2139	4700	01R-01J-02J
	EURO LOCKS	Ford Ranger Truck EU24 (2T-7W)	-	-	2138	4692	01R-01J-02J
	IFAM 	Ifam WX1000 (6+5+5)		000001-108570	2132	4457	01R-01J-02J
	IFAM 	HUNO (5P)	HU.....	0001-5715	9484	4693	01V
	INN 	INN PRO/BASIC Master	-	-	2135	4689	01R-01J-02J
	INN 	INN PRO/BASIC CT	-	-	2136	4690	01R-01J-02J
	KABA	Kaba 20 KA2 (4A)	-	-	154	1514	07R
	L&F - WHITCO		11...	001-232	9488	4703	01V
	L&F - WHITCO		14...	001-232	9489	4703	01V
	L&F - WHITCO		15...	001-232	9490	4703	01V
	L&F - WHITCO		16...	001-232	9491	4703	01V
	L&F - WHITCO		17...	001-232	9492	4703	01V
	L&F - WHITCO		18...	001-232	9493	4703	01V
	L&F - WHITCO		19...	001-232	9494	4703	01V
	L&F - WHITCO		20...	001-232	9495	4703	01V
	L&F - WHITCO		21...	001-232	9496	4703	01V
	L&F - WHITCO		22...	001-232	9497	4703	01V
	L&F - WHITCO		23...	001-232	9498	4703	01V
	L&F - WHITCO		24...	001-232	9499	4703	01V



FUTURA PRO NEWS WEB



L&F - WHITCO		25...	001-232	9500	4703	01V
L&F - WHITCO		26...	001-232	9501	4703	01V
L&F - WHITCO		27...	001-232	9502	4703	01V
L&F - WHITCO		28...	001-232	9503	4703	01V
MLS	MLS KT122 ELITE 2 FP 6+5P		00000016- 05000006	2131	2242	01R-01J-02J
MLS	MLS KT053 ELITE 1 (6P) - Red Line		XM01ZP24- XM01NDJ8	2133	1851	01R-01J-02J
MLS	MLS KT053 ELITE 1 (6P) - Red Line		000016-375006	1144	1851	01R-01J-02J
MLS	MLS KT152-MLS 6P FAMILY-RED LINE FP2		0000096-1199986	9474	1872	01V
MLS	MLS KT052-MLS- 6P Antibumping Final FP2		0000096-1199986	9478	1872	01V
PC Cortellezzi	PC Cortellezzi SY30.SY32, SY35 - C11 NEW	-	-	2137	4360	01R-01J-02J

August 2019

1_2019 FUTURA V.3.16.0 – FUTURA PRO V.3.18.0



■ Solved a minor Software problem (SN 121)

NEW SYSTEMS

	LOCK MANUFACTURER	LOCK SYSTEM	PROFILE	SERIES	SN	DATA CARD	CLAMP
	ABUS	ABUS A93 (5P)	AC.....X	00001-30000	9482	4684	01V
	CHERY			1234	9480	4676	01V
	CANTOL	MEGA 990 (5+5P)	-	-	2119	4675	01R-01J-02J
	FORTE	ENIGMA (2T-4)	-	-	2129	4686	01R-01J-02J
	CHICAGO			0123456789	9483	4685	01V
	GUARD	Profile G17 T6		00001-99999	9476	666	01V
	GREAT WALL	Great Wall (2T-8W)	-	-	2127	4681	01R-19J-02J
	GREAT WALL	Great Wall (2T-8W)	-	-	2130	4683	01R-01J-02J
	IFAM	F5S			8532	2336	01V
	LUXGEN			1235	9481	4679	01V
	MHA	MOD 31 (6P)			2120	4673	01R-01J-02J
	MLS 	MLS KT115 Standard FP2 5P		000001-012990	9470	2273	01V
	MLS 	MLS KT117 Standard FP2 6P		0000016-0756556	9471	2764	01V
	MLS 	MLS KT119 MLS FP2 6P		0000016-1200006	9473	1872	01V
	MLS 	MLS KT130 ELITE 1 FP2 6P		000016-857986	2117	1851	01R-01J-02J
	MLS 	MLS KT138 FAMILY FP2 6P		0000016-1209996	9472	1872	01V
	MLS 	MLS KT122 ELITE 2 FP2 6+5P		00000016-05000006	2115	2242	01R-01J-02J



FUTURA PRO NEWS WEB



NATIONAL	NATIONAL		0001-1378	9477	1043	01V
PAPAIZ	143CR R68 Multiponto(9+5)	-	-	2122	4678	01R-01J-02J
PREFER	Prefer IAA (5+6+5)	IAA.....	800001-801090	2123	4682	01R-01J-02J
R.O.C.	R.O.C. CH9T-(10P)		7654321	989	2660	02R
STANDERS	STANDERS (6p)	-	-	21146	1857	01R-01J-02J
TRAVEX	970 XT (7P)	-	-	2118	4674	01R-01J-02J
US-LOCK				9475	4012	01V
VOLVO	HU152S16 (2T- 10W)	-	-	2125	4680	01R-19J-02J
VOLVO	HU152S16 (2T- 10W)		4001-9001	2126	4680	01R-19J-02J
WINKHAUS 	WINKHAUS RPE/RPS	-	-	1323	3364	01R-25J-26J
YALE	Yale 1010		123456789AB	9479	4672	01V



FUTURA PRO NEWS WEB



July 2019

1_2019 FUTURA V.3.15.2– FUTURA PRO V.3.17.2



■ Solved a minor Software problem (Winkhaus RPE/RPS SN 1323)

June 2019

1_2019 FUTURA V.3.15.0 – FUTURA PRO V.3.17.0



■ Software improvements implemented, especially for the FUTURA AUTO version



■ Solved a minor Software problem

NEW SYSTEMS

	LOCK MANUFACTURER	LOCK SYSTEM	PROFILE	SERIES	SN	DATA CARD	CLAMP
	BEST	System:A2		1234546789	9019	4638	07V
	BEST	System:A3		123456	9171	4639	07V
	BEST	System:A4		12345	9452	4640	07V
	HAFELE	Hafele HW15R (2t-4W)	PL	3010-3999	2113	3061	01R-16J-17J
	HAFELE			3010-3010	9453	4642	01V
	HUWIL	Huwil HW15R (2t-4W)	-	-	1183	3061	01R-16J-17J
	KABA	Peaks A2 (0.150") (6P)		123456789	9012	4632	07V
	KABA	Peaks A2 (0.150") (6P)		123456789	9013	4633	07V
	KABA	Peaks A2 (0.150") (6P)		123456789	9014	4633	07V
	KABA	Peaks A2 (0.140") (6P)		123456789	9015	4634	07V
	KABA	Peaks A4 (0.150") (6P)		12345	9016	4635	07V
	KABA	Peaks A4 (0.150") (7P)		12345	9017	4636	07V
	KABA	Peaks A4 (0.140") (6P)		12345	9018	4637	07V
	TARONI 	TAR27P(Serie 5) (6p)		123456789	9010	4500	01V
	YALE	1000 SERIES FP2 (5P)	-	-	2104	3448	01R-13J-02J



FUTURA PRO NEWS WEB



	YALE	1000 EF 6P SHORT KEY	-	-	2105	4369	01R-13J-02J
	YALE	1000 SERIES FP2 LONG KEY-B (6P)	-	-	2106	3448	01R-13J-02J
	YALE	1000 SERIES SHORT KEY-A (6P)	-	-	1998	4369	01R-13J-02J
	YALE	2000 Series FP2 Short Key-A (5+5)	-	-	1346	3477	01R-01J-02J
	YALE	Yale YA99R (6+6)	-	-	1841	4222	01R-01J-02J
	YALE	500 SERIES FP2 (5P)		12345678	9011	3437	01V



FUTURA PRO NEWS WEB



April 2019

1_2019 FUTURA V. 3.14.0 – FUTURA PRO V. 3.16.0

NEW SYSTEMS

	LOCK MANUFACTURER	LOCK SYSTEM	PROFILE	SERIES	SN	DATA CARD	CLAMP
	EUROSECURE	EURO X Star	-	-	2096	4609	01R-05J-06J
	BAOJUN	BAOJUN (2T-10W)	-	-	2097	4616	01R-01J-02J
	FORD	Ford HU198T (2T-10W)		0020001-0032003	1956	4320	01R-01J-02J+A24
	Chang An	Chang An (2T-7W)	-	-	2098	4618	01R-01J-02J
	SECUREMME	EVO K1 (6P)	-	-	2100	4619	01R-01J-02J
	WAN JA	WAN JA (7P)	-	-	2101	4620	01R-01J-02J
	MAUER 	MLS KT155 Elite 2 E2 FP2 (6+5P)		000001-059000	2099	2242	01R-01J-02J
	ABUS	CeniT		CN11214-CN99894	9449	4617	01V
	RIELDA 	RS3		BL21ABAADPU O-	9356	3756	01V
	ABUS	Wavy line - Wavy line Pro		KLMZYX	3797	2689	01V
	CHANG AN	Chang An		ABCDE	9450	4622	01V
	CHANG AN			01234567	9008	4621	01V
	MAZDA			01234567	9451	4623	01V
	WILKA	W1		400001-499999	8040	740	01V



FUTURA PRO NEWS WEB



February 2019

1_2019 FUTURA V. 3.13.0 – FUTURA PRO V. 3.15.0

NEW SYSTEMS

	LOCK MANUFACTURER	LOCK SYSTEM	PROFILE	SERIES	SN	DATA CARD	CLAMP
	WILKA	Carat S3	-	-	1983	4359	01R-110-111
	WILKA	Carat S5	-	-	1984	4359	01R-110-111
	DOM	Dom IX TECO (Prf. 270)	-	-	2087	4566	01R-108-109
	DOM	Dom IX TECO (Prf. 271)	-	-	2088	4567	01R-108-109
	DOM	Dom IX7TE (Prf. 278)	-	-	2089	4568	01R-108-109
	DOM	Dom IX7TE (Prf. 274)	-	-	2090	4569	01R-108-109
	DOM	Dom IX7TE (Prf. 275)	-	-	2091	4570	01R-108-109
	DOM	Dom IX7TE (Prf. 273)	-	-	2092	4571	01R-108-109
	KABA	Kaba 10 (K10) (10+10+18)	-	-	483	1508	01R-1J-02J
	KABA	Kaba Gemini	-	-	75	1562	06R
	KABA	Kaba Gemini T 1.0 (K54)	-	-	90	1563	06R
	KABA	Kaba ExperT Cross S1.0a (K89A)	-	-	1731	4131	05R
	KABA	Kaba ExperT Cross S1.0b (K89B)	-	-	1733	4134	05R
	KABA	Kaba 20 KA2 (4A)	-	-	154	1514	07R
	KABA	Kaba Star (5A) old	-	-	304	1566	07R
	DOM	Dom IX TWIDO (Prf. 280)	-	-	2052	4506	01R-97J-98J
	DOM	Dom IX TWIDO (Prf. 281)	-	-	2053	4507	01R-97J-98J
	DOM	Dom IX7TW (Prf. 282)	-	-	2054	4508	01R-97J-98J
	DOM	Dom IX7TW (Prf. 283)	-	-	2055	4509	01R-97J-98J
	DOM	Dom IX7TW (Prf. 284)	-	-	2056	4510	01R-97J-98J
	DOM	Dom IX7TW (Prf. 285)	-	-	2057	4511	01R-97J-98J
	DOM	Dom IX7TW (Prf. 288)	-	-	2094	4588	01R-97J-98J



FUTURA PRO NEWS WEB



VAST	Vast (2T-8W)		0001-2648	2095	4591	01R-1J-02J
HON		...E	101-225	9411	4574	01V
FCV	FCV Stiftsatz B (5P)		123456789	9412	4579	01V
FCV	FCV Stiftsatz B (6P)		123456789	9413	4579	01V
SUZUKI			1001-2174	8762	3294	01V
CHRYSLER		VN....	0-1999	9321	745	01V
EURO LOCKS			48001-9000	6154	200	01V
HON		...E	100-111	8980	1069	01V
HON		...	100-111	8979	1069	01V
HON		...	405-550	8981	1069	01V
HON		...E	101-225	8983	1069	01V
HON		...H	101-225	8984	1069	01V
HON		...N	101-225	8985	1069	01V
HON		...R	101-225	8986	1069	01V
HON		E...	101-225	8987	1069	01V
HON		HON...	101-225	8988	1069	01V
HON		..	01-10	8989	1039	01V
HON		..E	01-10	8990	1039	01V
HON		HON..	01-10	8991	1039	01V
HON		L0..	01-10	8992	1039	01V
CX5	Scorpion (6P)		0123456789A	8993	4602	01V
HON		GG...	101-200	8982	1069	01V
TRIMARK		...	851-867	9414	138	01V
TRIMARK		CH...	501-550	9448	138	01V



FUTURA PRO NEWS WEB



TRIMARK		HC...	0-496	9415	138	01V
TRIMARK		RH...	001-050	9416	138	01V
TRIMARK		RH..	1-50	9417	138	01V
TRIMARK		TH..	1-25	9418	138	01V
TRIMARK		TH..	26-50	9419	138	01V
TRIMARK		TM...	851-867	9420	138	01V
TRIMARK		TR...	051-100	9421	138	01V
TRIMARK		TM...	301-323	9422	466	01V
TRIMARK		TM...	426-448	9423	466	01V
TRIMARK		...	101-150	9424	1030	01V
TRIMARK		...	151-200	9425	1030	01V
TRIMARK		...	201-250	9426	1030	01V
TRIMARK		...	500-650	9428	1030	01V
TRIMARK		...	51-100	9427	1030	01V
TRIMARK		...	901-950	9429	1030	01V
TRIMARK		TM...	101-150	9431	1030	01V
TRIMARK		TM...	151-200	9432	1030	01V
TRIMARK		TM...	201-250	9433	1030	01V
TRIMARK		TM...	500-650	9434	1030	01V
TRIMARK		TM...	51-100	9430	1030	01V
TRIMARK		TM...	901-950	9435	1030	01V
TRIMARK		TR....	1001-1098	9436	1030	01V
TRIMARK		TR....	1200-1259	9437	1030	01V
TRIMARK		J...	201-240	9445	4599	01V



FUTURA PRO NEWS WEB



	TRIMARK			1001-1240	9440	4598	01V
	TRIMARK			2001-2240	9441	4598	01V
	TRIMARK			3001-3240	9442	4598	01V
	TRIMARK			4001-4240	9443	4598	01V
	TRIMARK			5001-5240	9444	4598	01V
	TRIMARK		TA...	1-183	9446	4600	01V
	TRIMARK		...	700-729	9438	4066	01V
	TRIMARK		TM...	700-729	9439	4066	01V
	TRIMARK			80001-81000	9447	4601	01V
	HON		...	301-450	8994	1039	01V
	HON		...E	301-451	8995	1039	01V
	HON		...R	301-452	8999	1039	01V
	HON		...T	301-453	9000	1039	01V
	HON		...E	801-950	9001	1039	01V
	HON		HON...	301-455	9002	1039	01V
	HON		T...	301-456	9003	1039	01V
	HON		L...	700-824	9004	1039	01V
	HON		HG...	001-150	9005	1039	01V
	Clark	Clark Security (6P)		0123456789	9007	4602	01V



FUTURA PRO NEWS WEB



January 2019

1_2018 FUTURA V.3.1202 – FUTURA PRO V.3.14.0



- Problem with the Hebrew language solved.
- Problem with engraving solved.



FUTURA PRO NEWS WEB



Dicember 2018

1_2018 FUTURA V.3.11.0 – FUTURA PRO V.3.13.0

NEW SYSTEMS

	LOCK MANUFACTURER	LOCK SYSTEM	PROFILE	SERIES	SN	DATA CARD	CLAMP
	ASSA	Twin Combi (1T-5W)	-	-	907	2560	01R-01J-02J
	ABUS  PFAFFENHAIN	X12R (6+5)		X0100001- X0150000	2062	4525	01R-01J-02J
	ABUS 	D10X (6+7)		E00002A- E30000Z	2063	4540	01R-05J-06J
	BRICARD 	BRICARD DUAL XP S2	PL	XN.0342.10	2084	4562	01R-05J-06J
	MAGNUM	Magnum Superior (3+3)	-	-	4805	4575	01R-35J-36J
	MAGNUM	Magnum Superior (4+4)	-	-	4806	4576	01R-35J-36J
	MAGNUM	Superior+New(2T- 3W)	-	-	4807	4577	01R-01J-02J
	MAGNUM	Superior+New(2T- 4W)	-	-	4808	4578	01R-01J-02J
	MULT.LOCK	Mul-T-Lock Break Secure 3DS	-	-	2024	2242	01R-01J-02J
	ROYAL	Royal Enfield		2001-3170	9410	4560	V100
	HON	HON (5P)		101E-225E	9411	4574	V100

October 2018

1_2018 FUTURA V.3.10.0 – FUTURA PRO V.3.12.0

NEW FUNCTIONS



COPIES OF VEHICLE KEYS

This function is used to copy vehicle keys with standard or laser cuts, by means of facilitated searching.

IMPORTING HOOK POSITION FILE

This function is used to import a CSV file containing a list of positions for hooks associated to the Silca keys stocked by a point of sale/key-cutting centre. The file is imported from a USB PEN inserted into the key-cutting machine USB port.

Please note

For further details, download the FUTURA PRO Software Manual from the FUTURA PRO section of the Silca website (www.silca.biz).

BUG FIXED



Solved a minor Software problem.

NEW SYSTEMS

	LOCK MANUFACTURER	LOCK SYSTEM	PROFILE/SERIES	SERIES	SN	DATA CARD	CLAMP
	WILKA	Carat S1	-	-	1980	4358	01R-68J-69J
	WILKA	Carat S4	-	-	1986	4358	01R-68J-69J
	KABA 	Kaba K86 - matrix plus	-	-	2032	4468	06R
	KABA 	Kaba K91 - entro	-	-	2033	4469	06R
	M&C 	M&C Condor Mirror		M011A1001-M109A3169	2038	4435	01R-104-105
	M&C 	M&C Condor Mirror		M011B1001-M109B3169	2039	4435	01R-104-105
	M&C 	M&C Condor Mirror		M011C1001-M109C3169	2040	4435	01R-104-105
	M&C 	M&C Condor Mirror		M011D1001-M109D3169	2041	4435	01R-104-105
	M&C 	M&C Condor Mirror		M011E1001-M109E3169	2042	4435	01R-104-105



FUTURA PRO NEWS WEB



M&C	M&C Condor Mirror		M011F1001-M109F3169	2044	4435	01R-104-105
M&C	M&C Condor Mirror		M011G1001-M109G3169	2045	4435	01R-104-105
M&C	M&C Condor Mirror		M011H1001-M109H3169	2046	4435	01R-104-105
M&C	M&C Condor Mirror		M011K1001-M109K3169	2047	4435	01R-104-105
M&C	M&C Condor Mirror		M011M1001-M106M3169	2048	4435	01R-104-105
M&C	M&C Condor Mirror (Main+snake)	-	-	2049	4438	01R-104-105
M&C	M&C Condor Mirror (Main+side)	-	-	2050	4440	01R-104-105
M&C	M&C Condor Mirror (Main pins)	-	-	2051	4443	01R-104-105
M&C	M&C Condor Mirror (Snake)	-	-	2058	4444	01R-104-105
M&C	M&C Condor Mirror (Side)	-	-	2059	4445	01R-104-105
M&C	M&C Condor Mirror (Snake+Side)	-	-	2060	4512	01R-104-105
A.P.FER	Astral Sigillo W39	,,,,,HG	00001-38832	2064	1414	01R-05J-06J
A.P.FER	Astral Sigillo W39	,,,,,HI	00001-38832	2065	1414	01R-05J-06J
M&T	Astral Sigillo W41	,,,,,HM	00001-38832	2066	1414	01R-05J-06J
M&T	Astral Sigillo W41	,,,,,HP	00001-38832	2067	1414	01R-05J-06J
HUGO	HUGO GR 5S		6650000001-6650294740	2076	4548	01R-01J-02J
SECUREMME	SECUREMME K3.3 (5+5)	-	-	2077	4551	01R-13J-02J
KASSEL	NF 11 (6+5)		-	2078	4552	01R-01J-02J
TILANCO	Tilanco (5+5) (2T-3W)	-	-	2079	4531	01R-01J-02J
DOM	Dom IX Twinstar (Prof. 298)	-	-	2070	4542	01R-88J-89J
DOM	Dom IX Twinstar Std. Cut (Prof. 298)	-	-	2071	4543	01R-88J-89J
DOM	Dom IX Twinstar Prf. Cut (Prof. 298)	-	-	2072	4544	01R-88J-89J
DOM	Dom IX Twinstar (Prof. 299)	-	-	2073	4545	01R-88J-89J
DOM	Dom IX Twinstar Std. Cut (Prof. 299)	-	-	2074	4546	01R-88J-89J



FUTURA PRO NEWS WEB



	DOM🔒	Dom IX Twinstar Prf. Cut (Prof. 299)	-	-	2075	4547	01R-88J-89J
	KABA	Kaba Gemini (k50)	-	-	1096	2883	06R
	YALE	Superior 1 Star 10 Pin (2T-4W)	-	-	2080	4558	01R-01J-02J
	YALE	Platinum 3 Star 10 Pin (2T-4W)	-	-	2082	4558	01R-01J-02J
	YALE	Superior 1 Star 10 Pin (3+3)	-	-	2081	4559	01R-35J-36J
	YALE	Platinum 3 Star 10 Pin (3+3)	-	-	2083	4559	01R-35J-36J
	CCC			12345	9398	4460	01V
	KEYA			123	9399	4516	01V
	UEME			12345	9400	4518	01V
	SOPRANO			1234	9401	4519	01V
	WELKA			0123456789	9402	4520	01V
	BULLDOG			0123456	9403	4521	01V
	CISA			0123456789	9404	4522	01V
	SOPRANO	S-60		01234567	9405	4523	01V
	SOPRANO	S-25		0123	9406	4524	01V
	RIELDA🔒	RS3		BL21ABAADPUO- BL3OJAAERNN	9356	3756	01V
	EVERGOOD			123	9407	4526	01V
	SOBINCO			1234567	9408	4527	01V
	KEYA	-		234	8976	4532	01V
	CORNI	CC8		12345	8977	4533	01V
	STAM			012345	9409	4893	01V



FUTURA PRO NEWS WEB



August 2018

1_2018 FUTURA V.3.9.0 – FUTURA PRO V.3.11.0

NEW SYSTEMS

	LOCK MANUFACTURER	LOCK SYSTEM	PROFILE/SERIE S	SERIES	SN	DATA CARD	CLAMP
	ASSA ABLOY	Assa Abloy C310	-	12345678	9797	4505	01V
	LSDA	-	-	0123456789	9395	4493	01V
	LSDA	-	-	12345678	9396	4495	01V
	SUBARU	stop 4	-	30001-37850	9388	4459	01V
	CCC	-	-	12345	9398	4460	01V
	KEYA	-	-	123	9399	4516	01V
	UEME	-	-	12345	9400	4518	01V
	SOPRANO	-	-	1234	9401	4519	01V
	WELKA	-	-	0123456789	9402	4520	01V
	BULLDOG	-	-	0123456	9403	4521	01V
	CISA	-	-	0123456789	9404	4522	01V
	SOPRANO	S-60	-	01234567	9405	4523	01V
	SOPRANO	S-25	-	0123	9406	4524	01V
	RIELDA	RS3	-	BL21ABAADPUO- BL3OJAAERNN	9356	3756	01V
	EVERGOOD	-	-	123	9407	4526	01V
	SOBINCO	-	-	1234567	9408	4527	01V
	SILCA	Silca SK3 back side	-	-	2012	4407	01R-01J-02J
	SILCA	Silca SK3 side	-	-	2010	4395	01R-07J-08J
	HYUNDAI	Hyundai (2T- 8W)	-	0001-2500	2037	3336	01R-01J-02J
	Iseo	R11 PROGRESS	-	000001-061110	2061	1597	01R-11J-02J



FUTURA PRO NEWS WEB



	TITAN 	Titan T250 (6+5)	-	-	1461	3713	01R-01J-02J
	TITAN	Titan T100 X-R (4+4)	-	-	1248	3197	01R-50J-51J



FUTURA PRO NEWS WEB



June 2018

1_2018 FUTURA V.3.8.0 – FUTURA PRO V.3.10.0

NEW FUNCTIONS

NEW

SILCA SOFTWARE INTERFACE

The Silca Software Interface (SSI) function has been set up to run the production of master key system (MKS) in XML KESO and 'standard' DAT file formats ('special' DAT formats are not included).

Please note

For further details about the SSI function, download the FUTURA PRO Software Manual from the FUTURA PRO section of the Silca website (www.silca.biz)

NEW

 **OEM CLIENT ASSA®:** the OEM CLIENT function has been implemented for copying keys using data supplied by the manufacturer (OEM). At the moment the function runs the following ASSA® systems:

- ASSA dp
- ASSA Neptun
- ASSA Triton

Important Note

Users who wish to use the special OEM CLIENT function must make a request to both the manufacturer and Silca. Consult the Silca sales network for information regarding which manufacturers allow this function to be used.

When users have been authorised by the manufacturer and have applied to be enabled by SILCA they must unlock the OEM CLIENT function on board the machine by downloading a specific software update for their own FUTURA cutting machine.

After the software update, check that enabling has been activated by selecting the INFORMATION window and checking the ENABLE OEM section.

NEW SYSTEMS

	LOCK MANUFACTURER	LOCK SYSTEM	PROFILE/SE RIES	SERIES	SN	DATA CARD	CLAMP
	AGA 	Aga SLC (5+5)	-	-	2025	4346	01R-01J-02J
	AGA 	Aga SLX (5+4)	-	-	2026	4349	01R-01J-02J
	ASSA	Assa DP Sidecode	-	-	1095	2882	01R-68J-69J
	ASSA	Assa Neptun-Triton (Side Code)	-	-	1483	3553	01R-68J-69J
	DOM 	Dom IX6 SR E (Prf.234)	-	-	2019	4436	01R-01J-02J
	DOM 	Dom IX6 SR E (Prf.234) AT	-	-	2020	4437	01R-01J-02J



FUTURA PRO NEWS WEB



	FLEXON	FLEXON CS2100 (6P)	-	-	2027	4351	01R-01J-02J
	FLEXON	FLEXON CS2001 (5+5)	-	-	2028	4458	01R-01J-02J
	LINCE	Lince C3 (5+5)	-	-	864	2462	01R-24J-25J
	M&C	M&C Condor (Snake)	-	-	2022	4428	01R-82J-83J
	M&C	M&C Condor (Side)	-	-	2023	4429	01R-82J-83J
	M&T	M&T Champions Pro CP4 (C6LVJ2)	C6LVJ2... ...	C6LVJ200010 A -	2034	3802	01R-01J-02J
	MOTTURA	Mottura Project (6P)	-	-	2021	2982	01R-01J-02J
	ASSA	Cliq	-	123456789	3931	2880	01V
	ASSA	Neptun	-	123456789	4532	345	01V
	ASSA	Triton 5900	-	111111- 888888	4530	3822	01V
	CAS-CISA	-	-	1234	9380	4434	01V
	CEE	-	-	1234567	9378	4432	01V
	DOM	DOM 050-22	-	123456	8954	4476	01V
	DOM	DOM 050-22	-	123456	8955	4476	01V
	ERA	Fortress	6Y	300001- 398246	9381	4042	01V
	GLOBAL	-	-	123456	9377	4430	01V
	IBFM	Art.2260/60mm	-	123456789	9389	4470	01V
	IBFM	Art.2240/40mm	-	12345	9390	4471	01V
	IBFM	Art.2302/OL/54mm	-	123456	9391	4472	01V
	IBFM	Art.2215/15mm	-	12345678	9392	4473	01V
	IBFM	Art.2220/20mm	-	123456	9393	4474	01V
	IBFM	Art.2225/25mm	-	12345	9394	4475	01V
	INFINITI/NISSAN	stop 4	-	1-22185	9386	4459	01V
	INFINITI/NISSAN	stop 4	-	40001-41518	9387	4459	01V



FUTURA PRO NEWS WEB



	KABA	PX-PXP	-	1234567890	8941	3706	01V
	MAUER	S1	-	123456789	9379	4433	01V
	NISSAN	stop 4	-	1-22185	9385	4451	01V
	NISSAN	stop 4	-	1-22185	9388	4460	01V
	RIELDA	RS3	-	BL21ABAADPU O-	9356	3756	01V
	TITAN	Titan K6TL (6P)	-	123456789	8952	2202	01V

April 2018

1_2018 FUTURA V.3.7.0 – FUTURA PRO V.3.9.0

NEW SYSTEMS

	LOCK MANUFACTURER	LOCK SYSTEM	PROFILE/SERIES	SERIES	SN	DATA CARD	CLAMP
	ABUS 	ABUS BRAVUS PRO 1000(SHOULDER STOP)	-	-	1963	4325	01R-29J-30J
	ABUS 	ABUS BRAVUS PRO 3000(SHOULDER STOP)	-	-	1964	4326	01R-29J-30J
	ABUS 	ABUS BRAVUS PRO 2000(SHOULDER STOP)	-	-	1965	4327	01R-29J-30J
	ABUS 	ABUS BRAVUS PRO 4000(SHOULDER STOP)	-	-	1966	4328	01R-29J-30J
	ABUS 	ABUS BRAVUS PRO 3000(TIP STOP)	-	-	1958	4321	01R-29J-30J
	ABUS 	ABUS BRAVUS PRO 1000(TIP STOP)	-	-	1959	4322	01R-29J-30J
	ABUS 	ABUS BRAVUS PRO 2000(TIP STOP)	-	-	1960	4323	01R-29J-30J
	ABUS 	ABUS BRAVUS PRO 4000(TIP STOP)	-	-	1962	4324	01R-29J-30J
	VACHETTE	V-DIS Courte A	-	-	1996	4369	01R-13J-02J
	VACHETTE	V-DIS Longue B	-	-	1997	3448	01R-13J-02J
	VACHETTE	YALE 1000 EF 6P	-	-	1998	4369	01R-13J-02J
	VACHETTE	V-DIS+	-	-	1999	4266	01R-01J-02J
	M&C 	M&C Color New (3+3)		1A0001-6M3600	2000	4332	01R-95J-96J
	VACHETTE	Vachette Vac153R (6P)	-	-	2011	4408	01R-01J-02J
	POTENT	Potent PT6RP	-	-	2013	4411	01R-01J-02J
	OJMAR	OJ18(6+2)	-	-	2014	4413	01R-01J-02J
	ABUS	ABUS BIKE 8N		00001-05166	1993	4366	01R-92J-93J
	M&C 	M&C Color New (2T-5W)		1A0001-6M3600	2001	4345	01R-01J-02J
	EUROLOCKS	dethleffs EU22RP (2T-6W)	-	-	2004	4350	01R-01J-02J
	EVVA 	EVVA 4KS (2T)	-	-	2009	4352	01R-07J-08J



FUTURA PRO NEWS WEB



TITAN	Titan K5+	-	-	1484	3737	01R-01J-02J
ABUS	Abus Vela Pro 2000	VE20.....	00001-30000	2015	4423	01R-01J-02J
ABUS	Abus Vela Pro 1000	VE10.....	00001-30000	2016	4424	01R-01J-02J
MAHINDRA	Mahindra (2T-8W)	-	-	2017	4425	01R-19J-02J
HYUNDAI	Hyundai (2T--8W)	-	-	2018	4427	01R-19J-02J
PUNDRA		W...	000-522	8947	561	01V
PUNDRA		W...	101-330	8948	561	01V
PUNDRA		W...	401-800	8949	561	01V
CES			0123456	9360	4401	01V
KEYRACK			0123456	9361	4402	01V
FAAB			12345678	9362	4404	01V
CES			1234567890	9363	4405	01V
BALINGLOCK			0123456789	9364	4406	01V
LOCKWOOD (AUS)			1234567890	9365	4410	01V
UAP			0123456789AB CDEFGHIL	9366	4412	01V
CORBIN	405/20	...	1234567	9367	4414	01V
CORBIN (AUS)			0123456789	9368	4415	01V
BURG			01234567	9369	4416	01V
MILA			1234567	9370	4418	01V
MASTER			012345678	9371	4419	01V
CIL LIL			0123456789AB C	9372	4420	01V
BURG			123456	9373	4421	01V
ABUS	Abus Titalium		123456	9374	327	01V
ELZETT	30/30		123456	9375	2274	01V



FUTURA PRO NEWS WEB



	TSS			012345678	9376	4426	01V
	KENWORTH		P....	1-1500	8950	287	01V

January 2018

1_2018 FUTURA V.3.6.0 – FUTURA PRO V.3.8.0

NEW FUNCTIONS



- The "User Model Editor" function has a new "Multiline" token (T13) for engraving text on a number of rows.

NEW SYSTEMS

	LOCK MANUFACTURER	LOCK SYSTEM	PROFILE/SERIES	SERIES	SN	DATA CARD	CLAMP
	PFAFFENHAIN 	ABUS PFAFFENHAIN S6+	-	-	9359	4364	01V
	PUNDRA		W...	000-522	8947	561	01V
	PUNDRA		W...	101-330	8948	561	01V
	PUNDRA		W...	401-800	8949	561	01V
	TESA 	Tesa TX70 (5+5+11)	-	-	1042	2770	01R-94J-83J
	TITAN	Titan K5-K55/CR T75 (275)		K55 00001- K55 23375	1985	2570	01R-01J-02J
	FF-FACCHINETTI	SY30-SY32-SY35- C11 New		2260001- 2301184	1987	4360	01R-01J-02J
	VEGA	VP-7	-	-	1988	4361	01R-01J-02J
	KABA 	Kaba ExperT pluS S 1.0a (K83A)-Swed		EM101000- EM105997	1989	3670	05R
	HYUNDAI	Hyundai Kona (2T- 8W)	H....	0001-2500	1990	4362	01R-01J-02J
	DOM	Dom IX6N	-	-	1991	4363	01R-01J-02J
	YALE	Yale 987 Plus	-	-	1992	4365	01R-01J-02J
	SCHLAGE	C999 Ultra	-	-	1994	4280	01R-01J-02J
	ABUS	Abus Bike 6N (4T- 6W)		0001-1000	1995	4368	01R-92J-93J



FUTURA PRO NEWS WEB



December 2017

1_2017 FUTURA v. 3.5.0 - FUTURA PRO v. 3.7.0

New Systems

	Lock Manufacturer	Lock System	Profile/Series	Series	SN	Data card	Clamp
	DOM	Dom IX Twinstar (Prof. 290-291)	-	-	1901	4273	01R-88J-89J
	DOM	Dom IX Twinstar Std. Cut (Prof. 290-291)	-	-	1968	4333	01R-88J-89J
	DOM	Dom IX Twinstar Prf. Cut (Prof. 290-291)	-	-	1969	4334	01R-88J-89J
	WINKHAUS	Winkhaus X-TRA Inclined (5P)	-	-	703	1856	R30-80J-81J
	IBFM	IBFM 2304/CS (5P)	-	-	1976	4344	01R-01J-02J
	APECS	AP 3 Star	-	-	1977	4343	01R-01J-02J
	CISA	Cisa AP4 Pmec-C KA	PMEC-C-KA	XN.0326.10	1861	4230	01R-05J-06J
	CISA	Cisa AP4 Pmec-A KA	PMEC-A-KA	XN.0327.10	1862	4230	01R-05J-06J
	CISA	Cisa AP4 Pmec-9 KA	PMEC-9-KA	XN.0328.10	1863	4230	01R-05J-06J
	CISA	Cisa AP4 Pmec-6 KA	PMEC-6-KA	XN.0329.10	1864	4230	01R-05J-06J
	CISA	Cisa AP4 Pmec-5 KA	PMEC-5-KA	XN.0330.10	1865	4230	01R-05J-06J
	CISA	Cisa AP4 Pmec-3 KA	PMEC-3-KA	XN.0331.10	1866	4230	01R-05J-06J
	CISA	Cisa AP4 Pmec-C CA	PMEC-C-CA	XN.0335.10	1970	4230	01R-05J-06J
	CISA	Cisa AP4 Pmec-A CA	PMEC-A-CA	XN.0336.10	1971	4230	01R-05J-06J
	CISA	Cisa AP4 Pmec-9 CA	PMEC-9-CA	XN.0337.10	1972	4230	01R-05J-06J
	CISA	Cisa AP4 Pmec-6 CA	PMEC-6-CA	XN.0338.10	1973	4230	01R-05J-06J
	CISA	Cisa AP4 Pmec-5 CA	PMEC-5-CA	XN.0339.10	1974	4230	01R-05J-06J
	CISA	Cisa AP4 Pmec-3 CA	PMEC-3-CA	XN.0340.10	1975	4230	01R-05J-06J
	TITAN	Titan K5-K55/CR T75 (275)		001C-23375C	1979	2570	01R-01J-02J
	ISEO	Iseo R7 Leroy Merlin (5+6+6)		000001-428306	1982	868	01R-01J-02J
	DOM	Dom IXSATS(Pr.169- 170-171-172)(Precod)	-	-	1506	3788	01R-91J-02J



FUTURA PRO NEWS WEB



DOM	Dom IXSATS (Prof. 169)	-	-	1507	3789	01R-91J-02J
DOM	Dom IXSATS (Prof. 170)	-	-	1508	3790	01R-91J-02J
DOM	Dom IXSATS (Prof. 171)	-	-	1509	3791	01R-91J-02J
DOM	Dom IXSATS (Prof. 172)	-	-	1510	3792	01R-91J-02J
DOM	DOM IXSATS (Prof. 167)	-	-	1644	3929	01R-91J-02J
INN	INN (Pr.169-170-171-172)(Precoded)	-	-	1637	3992	01R-91J-02J
INN	INN (Prof. 169)	-	-	1638	3993	01R-91J-02J
INN	INN (Prof. 170)	-	-	1639	3994	01R-91J-02J
INN	INN (Prof. 171)	-	-	1640	3995	01R-91J-02J
INN	INN (Prof. 172)	-	-	1641	3996	01R-91J-02J
INN	INN (Prof. 167)	-	-	1645	4008	01R-91J-02J
RIELDA	RS3		BL21AJAADMYU-BL28FEAAEHTJ	9356	3756	01V
RIELDA	RS4-RS5		ABBA2010000-ABEL9917211	9358	3757	01V
FORD AUS	-		123456	9354	4337	01V
ABUS	TI12-TI14	TD.....	00001-02000	9266	3908	01V
ASSA/ABLOY	ASSA ABLOY SCD(6P)		ABCDEFGHJ	9357	345	01V
DOM	Dom 7D	7D...	001-200	4418	4353	01V
OMR	-		12	9355	4354	01V

November 2017 1_2017 FUTURA v. 3.4.1 - FUTURA PRO v. 3.6.1

Problems Solved



- Problem solved relating to cutting EVVA 4KS

October 2017 1_2017 FUTURA v. 3.4.0 - FUTURA PRO v. 3.6.0

Problems Solved



- Problem solved in the 'Copy from Original' function for flat keys.

New Functions

- **OEM CLIENT EVVA®:** the OEM CLIENT function has been implemented for copying keys using data supplied by the manufacturer (OEM). At the moment the function runs the following EVVA® systems:
 - Evva 3KS - 3KS+
 - Evva 4KS

Important Note

Users who wish to use the special OEM CLIENT function must make a request to both the manufacturer and Silca. Consult the Silca sales network for information regarding which manufacturers allow this function to be used.

When users have been authorised by the manufacturer and have applied to be enabled by SILCA they must unlock the OEM CLIENT function on board the machine by downloading a specific software update for their own FUTURA cutting machine.

After the software update, check that enabling has been activated by selecting the INFORMATION window and checking the ENABLE OEM section.

NEW



FUTURA PRO NEWS WEB



New Systems

	Lock Manufacturer	Lock System	Profile/Series	Series	SN	Data card	Clamp
	INAFER	INAFER (5P+6P)	-	-	1917	4280	01R-01J-02J
	asec-security	Asec 6P Dimple	-	-	1921	4286	01R-01J-02J
	HUGO	HUGO GR 4S	-	-	1919	4284	01R-01J-02J
	HUGO	HUGO GR 3.5S	-	-	1920	4285	01R-01J-02J
	Superlock	Superlock SL 11/15 (4+4)	-	-	1922	4287	01R-35J-36J
	GEVY	GEVY 5 PINS	-	-	1924	4290	01R-01J-02J
	GEVY	GEVY 6 PINS	-	-	1925	4292	01R-01J-02J
	GEVY	GEVY 11 PINS	-	-	1927	4293	01R-01J-02J
	DOM 	Dom Sigma Plus (Prof. 146)	-	-	1926	4294	01R-31J-32J
	RAV-BARRIACH	LOCXIS/ILA	-	-	1928	4296	01R-01J-02J
	APECS	Apecs RT-110(50/60C)-C-G (6P)	-	-	1929	4297	01R-01J-02J
	MAGNUM	Magnum 6P	-	-	1930	4299	01R-01J-02J
	Titan	Titan K5-K55/CR T75 (275)	L.....	00001-56331	1931	2570	01R-01J-02J
	IBFM	IBFM 2304/CS	-	-	1932	4300	01R-01J-02J
	IBFM	IBFM 2306	-	-	1934	4302	01R-01J-02J
	IBFM	IBFM 2309	-	-	1933	4301	01R-01J-02J
	CES 	POLLUX WZ (6+5+6)	-	-	1935	4303	01R-05J-06J
	CES 	POLLUX WZ (7+6+7)	-	-	1936	4304	01R-05J-06J
	MUL.T.LOCK	Mul-T-Lock MT5 (L)(19D)	-	-	1937	4305	01R-01J-02J
	MUL.T.LOCK	Mul-T-Lock MT5+ (L)(19D)	-	-	1938	4306	01R-01J-02J
	MUL.T.LOCK	Mul-T-Lock MT5+ (R)(19D)	-	-	1939	4307	01R-01J-02J
	MUL.T.LOCK	Mul.T.Lock Interactive (262)(19D) Mul.T.Lock Interactive (264)(19D) Mul.T.Lock Interactive (248)(19D)	-	-	1940 1941 1942	4308	01R-01J-02J
	MUL.T.LOCK	Mul.T.Lock Interactive (115) MK	-	-	1943	4309	01R-01J-02J
	MUL.T.LOCK	Mul.T.Lock (9mm-R)(19D)	-	-	1944	4310	01R-01J-02J
	MUL.T.LOCK	Mul.T.Lock Junior/Classic (19D) Mul.T.lock Gardesa Lion(19D)	-	-	1945 1946	4311	01R-01J-02J
	MUL.T.LOCK	Mul.T.Lock (9mm-L)(19D)	-	-	1947	4312	01R-01J-02J
	MUL.T.LOCK	Mul.T.Lock Interactive (225)(19D) Mul.T.Lock Interactive (223)(19D)	-	-	1948 1949	4313	01R-01J-02J
	MUL.T.LOCK Corbin Goldstar	Mul-T-Lock MT5 (R)(19D) Corbin Goldstar(19D)	-	-	1950 1951	4314	01R-01J-02J
	MUL.T.LOCK	Mul.T.Lock Interactive (206)(19D)	-	-	1952	4315	01R-01J-02J
	MUL.T.LOCK	Mul.T.Lock (8.8mm-R)(19D)	-	-	1953	4316	01R-01J-02J
	MUL.T.LOCK	Mul.T.Lock Interactive (215)(19D)	-	-	1954	4317	01R-01J-02J
	MUL.T.LOCK	Mul.T.Lock Interactive (115)(19D)	-	-	1955	4318	01R-01J-02J
	MG MONTI 	MG ST-KO9	-	-	1889	4263	01R-01J-02J
	YALE	Yale 2100	-	-	1895	4266	01R-01J-02J
	FAB-HUF	VAG High (4T-10W+4W)	-	-	1892	4264	01R-56J-57J
	Superlock	Superlock SL 11/15 (2T-3W)	-	-	1923	4288	01R-01J-02J
	M&C 	M&C Condor (snake+side pins)	-	-	1957	4319	01R-82J-83J



FUTURA PRO NEWS WEB



	OGDEN	Ogden Axial 45 (7P)		24568ABCDEFGHJI	446	1789	02R
	OGDEN	Ogden Axial 40 (7P)		24568ABCDEFGHJI	445	1790	02R
	Ford	Ford Fiesta 2017	-	-	1956	4320	01R-01J-02J
	AGENT	Agent NEW GMD-500 (5+5+5)	-	-	1967	4329	01R-01J-02J
	DOM	Dom Sigma Plus(Prof. 146)		01234567	8972	4295	01V
	IBFM	IBFM SERIE 2300		12345678	9353	594	01V



FUTURA PRO NEWS WEB



September 2017

1_2017 FUTURA v. 3.3.0 - FUTURA PRO v. 3.5.0

Problems Solved



- A decoding problem with the mobile tracer has been solved

New Functions



■ NEW FUNCTION: ENGRAVING.

The ENGRAVING function software comes free for all FUTURA PRO and FUTURE key-cutting machine models.

The ENGRAVING function requires the following accessories:

Jaw 01E

Jaw 02E

Cutter 18DW (specific for engraving)

Accessories for the FUTURA PRO ENGRAVING model are STANDARD and OPTIONAL for all other FUTURA and FUTURA PRO models.

The function is enabled by default. To disable and to hide certain engraving keys and fields, edit the parameter in the section: OPTIONS menu -> Settings -> Options -> Preferences DIMPLE/LASER keys

■ IMPROVED DECODING OF SYMMETRICAL VEHICLE KEYS

To solve installation difficulties encountered with symmetrical vehicle keys on side A or B of the standard clamp, the user may select the key blank before decoding the key. In this way the machine will indicate the best side of the clamp (C or D) on which to fit the key and can run the decoding operation successfully.



FUTURA PRO NEWS WEB



New Systems

Lock Manufacturer	Lock System	Profile/Series	Series	SN	Data card	Clamp
KESO	Keso K3000 Syst. 5 / Var. 6 (5 Axis)	-	-	259	2265	01R-26J-27J
ASSA	ASSA ABLOY K100	-	000001-117649	1870	4239	01R-86J-87J
IKON	IKON RW6	-	000001-117649	1871	4239	01R-86J-87J
UNION	Union KeyPRIME	-	000001-117649	1873	4239	01R-86J-87J
ASSA	Assa ABLOY CY110	-	000001-117649	1874	4239	01R-86J-87J
VACHETTE	Vachette Vercy	-	000001-117649	1877	4239	01R-86J-87J
IKON	IKON RW6 Main+Side Row	-	01000001-64117649	1875	4241	01R-86J-87J
DOM	Dom IX Saturn (Prof.140)	-	-	1247	3195	01R-01J-02J
DOM	Dom IX Saturn (Prof.168)	-	-	1494	3765	01R-01J-02J
KESO	Keso K3000S (Step-Drilling)	-	-	601	1571	01R-26J-27J
KESO	Keso K1000S (Step-Drilling)	-	-	599	1570	01R-26J-27J
PREFER	Prefer A (4+2)	A	001-330	1885	4261	01R-01J-02J
PREFER	Prefer AA (5+5)	AA	001-331	1883	4259	01R-01J-02J
PREFER	Prefer DAA (6+4+5)	DAA	800001-891280	1882	4252	01R-01J-02J
PREFER	Prefer EAA (6+3+3)	EAA	800001-852160	1884	4260	01R-01J-02J
PREFER	Prefer GAB (4+2+3)	GAB	800001-804410	1880	3941	01R-01J-02J
PREFER	Prefer HAA (5+5+4)	HAA	800001-800468	1881	4250	01R-01J-02J
ELZETT	X11 (6+3+2)	-	-	1887	4262	01R-01J-02J
A.P.FER	A.P.FER CHAMPIONS PRO (CP4-JP)	C6JLP	00010-C6LJP003G9	1893	3802	01R-01J-02J
Mul.T.Lock	Mul.T.Lock Interactive	-	-	1894	4267	01R-01J-02J
Abus	Abus EC660	A-Z	00001-30000	1900,1902-1915	4063	01R-05J-06J
WINKHAUS	WINKHAUS on-TRA (EGS)	-	-	1667	4060	01R-78J-79J
CISA	Cisa Astral Tekno CE P-S (Special Prof.)	(XN027710)	000001P-012070S	1691	3533	01R-74J-75J
CISA	Cisa Astral Tekno Special Profiles	(XN026210)	000002-194160	1359	3533	01R-74J-75J
BRICARD	Bricard Serial XP Special Profiles	(XN026210)	000002-194160	1360	3533	01R-74J-75J
CISA	Cisa Astral Tekno CA (Special Profiles)	(XN026710)	000008T-194155U	1690	3533	01R-74J-75J
KIA	Kia (2T-- 8W)	C	0001-2900	1886	4129	01R-01J-02J
TRIMARK	TriMark (2T-6W)	-	-	1888	4203	01R-19J-02J
BMW	Bmw (2T-8W)	-	10-81000	1890	1842	01R-01J-04J
FAB	FAB (2T-4W)	-	-	1891	4265	01R-01J-02J
FAB	VAG Mid (4T-9W+3W)	-	-	1706	4105	01R-56J-57J
KIA	Kia (2T - 8W)	JA	1001-3500	1916	3336	01R-01J-02J
UAP	UAP Kinetica		0123456789A	8964	4246	01V
UAP	UAP 35mm cyl.		0123456789A	8962	4246	01V
PUNDRA		B...	101-330	8961	561	01V
WILKA	Wilka TH6 PR100		200270-255966	8965	2952	01V
ABUS		V65...	1-331		730	01V
GREATWALL			45678	8966	4251	01V
YALE	Yale Jixin		123456	8998	4253	01V
CDP			0123456	9065	4254	01V
BAB			0123456789A	8968	4255	01V
GELEM	SP148		01234567	8969	4256	01V



FUTURA PRO NEWS WEB



June 2017

1_2017

FUTURA v. 3.2.1 - FUTURA PRO v. 3.4.1

Problems Solved



■ Solved some problems. We suggest to install this version.



FUTURA PRO NEWS WEB



June 2017

1_2017 FUTURA v. 3.2.0 - FUTURA PRO v. 3.4.0

New Functions

■ **OEM CLIENT MOTTURA®:** the OEM CLIENT function has been implemented for copying keys using data supplied by the manufacturer (OEM). At the moment the function runs the following MOTTURA® systems:

- Champions C10
- Champions C28 - C29
- Champions C2J - C2K
- Champions C30 - C31
- Champions C34 - C35
- Champions C38
- Champions C43 - C44
- Champions C4J - C4K
- Champions CP4 - CM7
- Champions CP4 Armo & Riarmo
- Champions CP4 Matic
- Champions CP4 Armo&Riarmo Attiva/Disattiva
- Champions C28 Plus
- Champions C39
- Champions C43 Plus

Important Note

Users who wish to use the special OEM CLIENT function must make a request to both the manufacturer and Silca. Consult the Silca sales network for information regarding which manufacturers allow this function to be used.

When users have been authorised by the manufacturer and have applied to be enabled by SILCA they must unlock the OEM CLIENT function on board the machine by downloading a specific software update for their own FUTURA cutting machine.

After the software update, check that enabling has been activated by selecting the INFORMATION window and checking the ENABLE OEM section.

■ **Queue of Job Function:** the Queue of Job function has been revised to take into account new software developments. At the moment it is divided into:

- STANDARD queue with current functionalities but new graphics
- OEM queue for OEM jobs only

Important Note

For further details about the OEM CLIENT function and Job Queue, download the FUTURA PRO Software Manual from the Silca website, FUTURA PRO section (www.silca.biz)





FUTURA PRO NEWS WEB



New Systems

	Lock Manufacturer	Lock System	Profile/Series	Series	SN	Data card	Clamp
	AMIG	Amig (6+6)	-	-	827	2395	01R-01J-02J
	FIAM	Fiam Logic 17(5+5)	-	-	1049	2780	01R-66J-67J
	FIAM	Fiam Logic 18/19(5+5)	-	-	1050	2781	01R-66J-67J
	WANJIN	Wanjin WJ1R (620-7P)	-	-	1814	4193	01R-01J-02J
	WANJIN	Wanjin WJ1R (650-7P)	-	-	1815	4194	01R-01J-02J
	WANJIN	Wanjin WJ1R (530-7P)	-	-	1816	4196	01R-01J-02J
	IBFM	ibfm 2303/CS	-	-	1817	4197	01R-01J-02J
	MSM	MSM GPI1 (7P)	-	-	1818	4200	01R-01J-02J
	APECS	APECS APK2R (6P)	-	-	1819	4202	01R-01J-02J
	GATEMATE	Gatemate (6P)	-	-	1823	4204	01R-01J-02J
	WINKHAUS	Winkhaus X-TRA (5+5)	-	-	526	1444	01R-80J-81J
	M&C	M&C Condor (Main+side pins)	-	-	1831	4218	01R-82J-83J
	M&C	M&C Condor (Main pins)	-	-	1867	4233	01R-82J-83J
	M&C	M&C Condor (Main + snake)	-	-	1868	4234	01R-82J-83J
	LIPS	Lips 2000 Octro (5A)	-	-	663	1829	01R-01J-02J
	YALE	Yale YA99R (6+6)	-	-	1841	4222	01R-01J-02J
	KESO	K8000 Omega^2 Syst. 9 / Var. 44	-	-	1849	4224	01R-01J-02J
	MUL.T.LOCK	Mul.T.Lock Gardesa Tiger (7P)	-	-	1543	1504	01R-01J-02J
	MUL.T.LOCK	Mul.T.Lock interactive (223)	-	-	1845	956	01R-01J-02J
	MUL.T.LOCK	Mul.T.Lock interactive (248)	-	-	1846	889	01R-01J-02J
	MUL.T.LOCK	Mul.T.Lock Junior/Classic	-	-	646	1632	01R-01J-02J
	MUL.T.LOCK	Mul.T.Lock Gardesa Lion	-	-	1844	1632	01R-01J-02J
	MUL.T.LOCK	Mul.T.Lock integrator	-	-	1843	1504	01R-01J-02J
	HOK	HOK HOK2R (6P)	-	-	1850	4227	01R-01J-02J
	CISA	CISA AP4 PG	PG	XN.0310.10	1851	4228	01R-05J-06J
	CISA	CISA AP4 PG 3L	PG	XN.0317.10	1853	4228	01R-05J-06J
	CISA	CISA AP4 PG 3C	PG	XN.0318.10	1854	4228	01R-05J-06J
	CISA	CISA AP4 PG CA	PG	XN.0319.10	1855	4228	01R-05J-06J
	CISA	CISA AP4 PG P/S	PG	XN.0320.10	1856	4228	01R-05J-06J
	CISA	CISA AP4 PE	PE	XN.0321.10	1852	4229	01R-05J-06J
	CISA	CISA AP4 PE 3L	PE	XN.0322.10	1857	4229	01R-05J-06J
	CISA	CISA AP4 PE 3C	PE	XN.0323.10	1858	4229	01R-05J-06J
	CISA	CISA AP4 PE CA	PE	XN.0324.10	1859	4229	01R-05J-06J
	CISA	CISA AP4 PE P/S	PE	XN.0325.10	1860	4229	01R-05J-06J
	TRELOCK	Trelock RS455-H2 (4T-4W)	-	-	1411	3639	01R-01J-02J
	EVVA	EVVA 4KS (1T)		987654321	1848	4226	01R-07J-08J
	KESO	Keso K3000 Syst.5 / Var.6 (3 Axis)	-	-	600	1567	01R-26J-27J
	LIPS	Lips 1000 Octro (5A)	-	-	678	1830	01R-26J-27J
	KABA	Kaba Miwa (11+11+10+10)	-	-	800	2349	01R-84J-85J
	KABA	Kaba Miwa New (11+11+10+10)	-	-	1342	3432	01R-84J-85J
	FEDERAL	YCF 35-35	6Y.....	200001-	9228	4042	01V
	MAZDA	-	-	10100-12283	8944	4231	01V
	GREATWALL	-	-	123	8945	4232	01V
	WINKHAUS	RPS+	-	0123456789	8903	4214	03V
	ASSA-ABLOY	Cylinder VIP+	-	1234567890	8943	4221	01V



FUTURA PRO NEWS WEB



	VACHETTE	HDI+/VMI+		1234567890	8831	3719	01V
	ASSA-ABLOY	Cylinder VMI		12345678	8942	4216	01V

Problems Solved



- Problem solved in decoding keys requiring a change of jaws.
- Cutting problem solved with cuts entered by the F9 function.



FUTURA PRO NEWS WEB



May 2017

1_2017 FUTURA v. 3.1.1 - FUTURA PRO v. 3.3.1

Problems Solved



- Solved a problem cutting more pieces of a key with only one cut axis.
- The number of cutting steps have been increased both for high security car keys and for edge keys.

April 2017

1_2017 FUTURA v. 3.1.0 - FUTURA PRO v. 3.3.0

Problems Solved



- Solved a problem related to the "Check installed key" function
- Solved a problem related to the decoding function
- Corrected data of the following SN:1791 (SUPERIOR -PLATINUM), 22 (LANCIA GT2), 83 (Mercedes HU64P '93 (2T-10W), 1482 (Dodge 2T-10W), 1602 (Mercedes HU64P 2T-10W), 2 (Alfa romeo GT2AP 5+5), **1199** (Assa D12 Serie 1200), **1356** (Lexus TOY48 2T-4W), **9085** (MITSUBISHI).

New Systems



Lock Manufacturer	Lock System	Profile/Series	SN	Data card	Clamp
ABUS 	Abus EC660	S00001B- S30000B	1803	4063	01R-05J-06J
ISEO 	Iseo R11 Progress	000001-038897	1820	1597	01R-11J-02J
ISEO 	Iseo R11 Progress (Cantiere)	000001-012977	1821	1597	01R-11J-02J
ISEO 	Iseo R11 Progress (Padronale)	100001-112977	1822	1597	01R-11J-02J
ABUS 	Abus vela 1000	VE10.....00001-30000	1770	4152	01R-01J-02J
ABUS 	Abus vela 2000	VE20.....00001-30000	1775	4156	01R-01J-02J
ABUS 	Abus xp20s	DXPY	1830	4217	01R-05J-06J
WINKHAUS 	Winkhaus ON-tra (P1)	-	1613	3938	01R-78J-79J
WINKHAUS 	Winkhaus ON-tra (P3)	-	1614	3939	01R-78J-79J
WINKHAUS 	Winkhaus ON-tra + (P1-P1)	-	1616	3943	01R-78J-79J
WINKHAUS 	Winkhaus ON-tra + (P1-P2)	-	1617	3944	01R-78J-79J
WINKHAUS 	Winkhaus ON-tra + (P1-P3)	-	1618	3945	01R-78J-79J
WINKHAUS 	Winkhaus ON-tra + (P1-P4)	-	1619	3946	01R-78J-79J
WINKHAUS 	Winkhaus ON-tra + (P1-P5)	-	1620	3947	01R-78J-79J
WINKHAUS 	Winkhaus ON-tra + (P1-P6)	-	1621	3948	01R-78J-79J
WINKHAUS 	Winkhaus ON-tra + (P1-P7)	-	1622	3949	01R-78J-79J
WINKHAUS 	Winkhaus ON-tra + (P1-P8)	-	1623	3950	01R-78J-79J
WINKHAUS 	Winkhaus ON-tra + (P3-P1)	-	1624	3951	01R-78J-79J
WINKHAUS 	Winkhaus ON-tra + (P3-P2)	-	1625	3952	01R-78J-79J
WINKHAUS 	Winkhaus ON-tra + (P3-P3)	-	1626	3953	01R-78J-79J
WINKHAUS 	Winkhaus ON-tra + (P3-P4)	-	1627	3954	01R-78J-79J
WINKHAUS 	Winkhaus ON-tra + (P3-P5)	-	1628	3955	01R-78J-79J
WINKHAUS 	Winkhaus ON-tra + (P3-P6)	-	1629	3956	01R-78J-79J
WINKHAUS 	Winkhaus ON-tra + (P3-P7)	-	1630	3957	01R-78J-79J
WINKHAUS 	Winkhaus ON-tra + (P3-P8)	-	1631	3958	01R-78J-79J
SSANGYONG	SSANGYONG (4T-6W)	KW1234	1813	2372	01R-01J-02J
LEXUS	Lexus TOY48P (4T-8W)	O0001-O5000	4801	480	01R-01J-02J
M&C 	M&C Matrix	.. 1A-9Z	1828	4209	R01-66J-67J
M&C 	M&C Condor	011A1001-109A3169	1826	4206	01R-82J-83J
M&C 	M&C Condor	011B1001-109B3169	1832	4206	01R-82J-83J
M&C 	M&C Condor	011C1001-109C3169	1833	4206	01R-82J-83J



FUTURA PRO NEWS WEB



M&C	M&C Condor	011D1001-109D3169	1834	4206	01R-82J-83J
M&C	M&C Condor	011E1001-109E3169	1835	4206	01R-82J-83J
M&C	M&C Condor	011F1001-109F3169	1836	4206	01R-82J-83J
M&C	M&C Condor	011G1001-109G3169	1837	4206	01R-82J-83J
M&C	M&C Condor	011H1001-109H3169	1838	4206	01R-82J-83J
M&C	M&C Condor	011K1001-109K3169	1839	4206	01R-82J-83J
M&C	M&C Condor	011M1001-106M3169	1840	4206	01R-82J-83J
HUF	BAIC Motors D50	-	1825	4186	01R-19J-02J
HUF	Mercedes HU126T (2T-10W)	-	1827	4207	01R-01J-04J
VALEO	Chang An (2T-7W)	-	1829	4212	01R-01J-02J
ASSA-ABLOY	C300	12345678	8808	4213	01V
MINDA		2001-3170	5840	4201	01V
ASSA-ABLOY	Gen-6 System	0123456789BHT	8809	4195	01V
MEDECO	KeyMark X4 7P	0123456789	8790	4059	01V
YALE	Serie 62000 60mm	0123456789	8789	4208	01V
SUZUKI		7701-8904	9351	157	01V



FUTURA PRO NEWS WEB



March 2017

1_2017 FUTURA v. 3.0.3 - FUTURA PRO v. 3.2.2

Problems Solved



- Fixed data card data of SN 1791 (SUPERIOR-PLATINUM), 22 (LANCIA GT2), 2 (ALFA ROMEO GT2AP), 83-1602 (MERCEDES HU64P), 1482 (DODGE).

March 2017

1_2017 FUTURA v. 3.0.1 - 3.0.2

Problems Solved



- Solved some problems. We suggest to install this version.

February 2017

1_2017 FUTURA v. 3.0.0 - FUTURA PRO v. 3.2.0

New Functions



- **Software performance greatly enhanced to make navigation and searches quicker**
- **New guided software update procedures implemented via tablet and USB PEN**
- CodeMaker function (option to buy) implemented for flat and dimple keys. Used to create data cards not yet included in the SILCA database
- F9 function introduced to facilitate entering combinations for KABA Expert keys
- Cutting review function introduced for laser-cut keys
- New simplified search implemented for automotive keys
- Function implemented for using any side of clamp 01V to cut symmetrical, flat double keys
- Method modified for cutting flat and laser keys by selecting the number of times the cutter passes

New Systems

Lock Manufacturer	Lock System	Profile/Series	SN	Data card	Clamp
YALE	Yale 1000 Series (5P)	1001-3640	1795	3448	01R-13J-02J
GERDA 	GERDA PROSystem	LP00162-LP17D99	1796	4181	01R-01J-02J
BASI/DOM 	Basi K10 (prof, 157)	-	1443	3694	01R-01J-02J
PREFER	Prefer (3+3W+2)	(3+3W+2)	303	1770	01R-01J-02J
MCM	Mcm 4SE MC10R (6P)	-	191	1510	01R-62J-63J
POTENT	POTENT 4000 Evolution	800001-830000	1800	4190	01R-13J-77J
POTENT	POTENT 4000 Evolution	800001-830000	1801	4190	01R-13J-77J
YALE 	YALE YL6 Main Row	-	1802	4191	01R-01J-02J
EUROSPEC	D69 Padlock	-	1673	4069	01R-01J-02J
EUROSPEC	D54 Chain Lock	-	1674	4070	01R-01J-02J
EUROSPEC	D74 U Lock	-	1675	4071	01R-01J-02J
EUROSPEC	D51 Cable Lock	-	1676	4072	01R-01J-02J
Lehmann	Lehmann Prestige B5		1559	3868	01R-76J-77J
Audi-VW	Audi-VW HU66P (2T-8W)	0001-6000	102	970	01R-03J-02J
Audi-VW-FORD-	FORD HU66P (2T-8W)	6001-8110	1798	970	01R-03J-02J
AUDI/PORSCHE/	HU66T6 (2T-9W) (D1)	6001-8110	1799	2399	01R-03J-02J
EURO LOCKS		50001-52000	6156	200	01V
MASTER		470K000-479K999	9326	3002	01V
MASTER		480K000-489K999	9327	3002	01V
MASTER		490K000-499K999	9328	3002	01V
MASTER		500K000-509K999	9329	3002	01V
MASTER		510K000-509K999	9330	3002	01V
MASTER		520K000-529K999	9331	3002	01V



FUTURA PRO NEWS WEB



MASTER		530K000-539K999	9332	3002	01V
MASTER		540K000-549K999	9333	3002	01V
MASTER		550K000-559K999	9334	3002	01V
MASTER		560K000-569K999	9335	3002	01V
MASTER		570K000-579K999	9336	3002	01V
MASTER		580K000-589K999	9337	3002	01V
MASTER		590K000-594K999	9338	3002	01V
MASTER		001-737	9339	4182	01V
MASTER		012345678	9340	4183	01V
BASTA		012345678	9341	4184	01V
MASTER		460K000-469K999	9342	3002	01V
CHICAGO		7K00-97	9343	1041	01V
MAZDA		0123	9344	4185	01V
MASTER		30H... 000-629	9345	526	01V
MASTER		32H... 169-620	9346	526	01V
MASTER		450K000-459K999	9347	3002	01V
BURG		19151-19350	9348	1643	01V
PUNDRA		P001-600	9349	4018	01V
PUNDRA		S01-59	9350	4019	01V

Problems Solved



■ Problem solved relating to cutting LEGALLAIS: SN 905



FUTURA PRO NEWS WEB



December 2016

1_2016 FUTURA v. 2.21.0 - FUTURA PRO v. 3.1.0

NEW SYSTEM

	Lock Manufacturer	Lock System	Profile/Series	SN	Card	Clamp
	ABUS	Abus Vela 1000	VE10.....00001-30000	1770	4152	01R-01J-02J
	ABUS	Abus Vela 2000	VE20.....00001-30000	1775	4156	01R-01J-02J
	AMIG	10000	-	1789	4176	01R-01J-02J
	BASI	Basi I6BM	B.....001-33938	1776	4157	01R-05J-06J
	DOM 	Dom IX6 SR S (prof. 250/251/252/253/254)	-	1779	4159	01R-44J-02J
	ERA	UCFTP (EA)	EA 400001-411502	1783	4173	01R-01J-02J
	ERA	UCFTP (EB)	EB 400001-411502	1787	4174	01R-01J-02J
	ERA	UCFTP (EC)	EC 400001-411502	1788	4175	01R-01J-02J
	HDS 	HDS WZ (6+5+6)	-	1677	4073	01R-05J-06J
	HDS 	HDS WZ (7+6+7)	-	1376	3562	01R-05J-06J
	ISEO 	R9 Plus	EDL 000001-350589	1790	868	01R-01J-02J
	MOIA	MCHGYPC (7+4+3)	-	1780	4170	01R-01J-02J
	MOIA	MCHGYPC-M (7+4+3)	-	1781	4171	01R-01J-02J
	MOIA	MCGHYPC-C (6+3+3)	-	1782	4172	01R-01J-02J
	SECUREMME 	Securemme EVOK64 (10 Pin)	-	1777	4158	01R-13J-02J
	SECUREMME 	Securemme EVOK22 (11 Pin)	-	1769	4150	01R-13J-02J
	SECUREMME 	Securemme EVOK64 (11 Pin)	-	1778	4150	01R-13J-02J
	YALE	Superior / Platinum (2T-4W)	-	1791	4179	01R-01J-02J
	YALE	Superior / Platinum (5+4)	-	1792	4180	01R-35J-36J
	YALE	Superior / Platinum (4+3)	-	1793	4180	01R-35J-36J
	YALE	Superior / Platinum (3+2)	-	1794	4180	01R-35J-36J
	SCHLAGE	AUB system	 1234567	9325	4151	01V
	M&C 	Matrix	 1A4001-6M8162	9323	4146	01V
	RENAULT-DACIA		 1234	9324	4145	01V

BUG FIXED



- Solved a problem related to the cutting of DOM: SN 1231, 1244 and 1245
- Solved a problem related to the 05V clamp
- Fixed data card data of SN 1402-1403 (FF-FACCHINETTI), 1632 (PREFER).
- Codes updated for SN 1235 (ISEO)

September 2016

1_2016 FUTURA v. 2.20.0

NEW FUNCTIONS



- The working mode of carter microswitch has been improved.


NEW SYSTEM

	Lock Manufacturer	Lock System	Profile/Series	SN	Card	Clamp
	KABA 	Kaba ExperT S 1.2b (K56B)	-	575	1606	05R
	KABA 	Kaba ExperT S 1.2a (K56A)	-	569	1607	05R
	KABA 	Kaba ExperT S 1.2a (K56A)	-	1542	1607	05R
	KABA 	Kaba ExperT pluS S 1.0a (K83A)	-	1425	3670	05R
	KABA 	Kaba ExperT pluS S 1.0b (K83B)	-	1430	3675	05R
	M&T 	M&T Champions Pro CP4 (C6LJ2)	C6LJ2.....C6LJ200010-C6LJ2003G9	1738	3802	01R-01J-02J
	M&T 	M&T Champions Pro CP4 (C6LJK)	C6LJK.....C6LJK00010-C6LJK003FJ	1739	3802	01R-01J-02J
	ABUS		GN 8510-9509	9322	538	01V

BUG FIXED



- Fixed data card data of SN 1688.
- New jaw "04V." for the cards (2658 V14-XY14-Y14) (3862 X6V) (3913 Vitess 1000) (3907 Vitess 2000) (3922 Vitess 4000)





FUTURA PRO NEWS WEB



July 2016

1_2016 FUTURA v. 2.19.0

NEW SYSTEM

	Lock Manufacturer	Lock System	Profile/Series	SN	Card	Clamp
	EURO LOCKS	EU21P (2T-7/8W)	-	1734	4133	01R-01J-02J
	FEDERAL	UCF3100	C 400001-414382	1727	4128	01R-01J-02J
	KIA	Kia (2T-- 8W)	KD 0001-3000	1728	4129	01R-01J-02J
	KIA	Kia (2T-- 8W)	D 0001-3000	1729	4129	01R-01J-02J
	TITAN	I6 (6P)	-	1725	4126	01R-05J-06J
	TONYON	TY340-STZ52-STB24-KB23 (4T-5W)	B 80001-81560	1672	4068	01R-01J-02J
	TRELOCK 	InX M2 (4T-4W)	M.....200001-210000	1722	4122	01R-01J-02J
	TRELOCK 	InX ML2 (4T-4W)	ML.....200001-210000	1723	4122	01R-01J-02J
	WITTE	Volvo XC90 (2T - 8W)	A001-F099	1726	4127	01R-01J-02J+A34 01R-19J-02J
	YARDENI	Yardeni 6 Master-No cut tip	-	1707	4107	01R-01J-02J
	YARDENI	Yardeni 6 Regular-Cut tip	-	1708	4108	01R-01J-02J
	YARDENI	Yardeni 6 Master-Cut tip	-	1709	4109	01R-01J-02J
	ABUS	Abus 83	0001-8900	9317	3908	01V
	ABUS	Abus U72	U72....1-1043	9318	729	01V
	ABUS	Abus U74	U74....1-1043	9319	729	01V
	ESETY 	Esety Omega	123456789	9315	4123	01V+B14
	PFAFFENHAIN	S5+	9876543210XYZ	9316	4124	01V
	RONIS		4001-5000	9320	206	01V

BUG FIXED

	- Fixed data card data of SN 750 (YARDENI), 1419-3145-3318 (EVVA) - Codes updated for SN 921-766 (HUF) - The problem regarding cutting the Esety Omega system (data card 1532 replaced by data card 4123) has been solved. - Solved a problem related to the cutting of FORD: SN 694, 1165 and 1513. - Solved a minor Software problem.
---	---



FUTURA PRO NEWS WEB



June 2016

1_2016 FUTURA v. 2.18.0

NEW SYSTEM

	Lock Manufacturer	Lock System	Profile/Series	SN	Card	Clamp
	GOAL	Goal GP (6+6+6)	-	1698	4089	01R-01J-02J
	GOAL	Goal GP (7+7+7)	-	1699	4090	01R-01J-02J
	OXLOC 	Oxloc O9,2	-	1700	4093	01R-29-30J
	OXLOC 	Oxloc O9,3	-	1701	4094	01R-29-30J
	OXLOC 	Oxloc O8,2 (4P)	-	1702	4095	01R-24-25J
	OXLOC 	Oxloc O8,3 (4P)	-	1703	4096	01R-24-25J
	VOLKSWAGEN SKODA	HU162T (4T-8W)	-	1704	4100	01R-56J-57J
	OXLOC 	Oxloc O8,2	9876543210XYZ	9297	4080	01V
	OXLOC 	Oxloc O8,3	9876543210XYZ	9296	4079	01V
	HUDSON		T001-050	9303	1039	01V
	HUDSON		G401-500	9304	1039	01V
	HUDSON		H0001-1000	9305	1039	01V
	HUDSON		AM0001-1000	9306	1039	01V
	HUDSON		C007-1000	9307	1039	01V
	HUDSON		PMI100-149	9308	1039	01V
	HUDSON		HL251-1495	9309	1039	01V
	MG (MONTI)	Chiave normale 4P	1234567	9310	4101	01V
	MG (MONTI)	Chiave normale 5P	1234567	9311	4101	01V
	MG (MONTI)	Chiave ridotta 5P	12345	9312	4102	01V
	MG (MONTI)	Chiave Simmetrica 6P	1234567	9313	4103	01V
	ESP		T0-1000	9314	561	01V

BUG FIXED



- Solved a problem related to the decoding of ABUS Bravus e OXLOC:
SN 1417, 1418, 1419, 1420, 1536, 1646, 1650, 1654, 1647, 1700, 1701.



FUTURA PRO NEWS WEB



May 2016

1_2016 FUTURA v. 2.17.0

NEW SYSTEM

	Lock Manufacturer	Lock System	Profile/Series	SN	Card	Clamp
	CISA 	Astral Tekno CA	(XN027510) 000008U-194155U	1688	3226	01R-05J-06J
	CISA 	Astral Tekno CE P-S	(XN027710) 000001P-012070S	1689	3226	01R-05J-06J
	GOAL	Goal V-18 Master NEW (6+6+6)	-	1698	4089	01R-01J-02J
	GOAL	Goal V-18 Master NEW (7+7+7)	-	1699	4090	01R-01J-02J
	ISEO 	R7 Extra Cantiere (Cantiere)	ECE 000001-039242	1692	868	01R-01J-02J
	ISEO 	R7 Extra Cantiere (Padronale)	ECE 100001-139242	1693	868	01R-01J-02J
	ISEO 	R7 Extra Ricifrabile (Cantiere)	EGG 000001-009744	1694	868	01R-01J-02J
	ISEO 	R7 Extra Ricifrabile (Padronale 1)	EGG 100001-109744	1695	868	01R-01J-02J
	ISEO 	Iseo R7 Extra Ricifrabile (Padronale 2)	EGG 200001-209744	1696	868	01R-01J-02J
	ISEO - DORMA	DEC261 SKG	EBM 000001-171276	1697	2176	01R-01J-02J
	MOTTURA	Champions Pro CP4-CM7	-	1679	3802	01R-01J-02J
	MOTTURA	Mottura Champions Pro CP4 Armo-Riarmo	-	1680	3803	01R-01J-02J
	MOTTURA	Mottura Champions Pro CP4 Matic	-	1681	3804	01R-01J-02J
	MOTTURA	Mottura Champions Pro CP4 Riarmo Att-Dis	-	1682	3805	01R-01J-02J
	MOTTURA	MOTTURA Champions C28 Plus	-	1683	4075	01R-01J-02J
	MOTTURA	MOTTURA Champions C39	-	1684	4076	01R-01J-02J
	MOTTURA	Mottura Champions C43 Plus	-	1685	4078	01R-01J-02J
	ASSA	Profile AS	AS0123456789	9285	345	01V
	ASSA	Profile PS	PF0123456789	9286	345	01V
	ASSA	Profile US	US0123456789	9287	345	01V
	ASSA	Profile HN	HN0123456789	9288	345	01V
	ASSA	Profile NK	NK0123456789	9289	345	01V
	ASSA	Profile GM	GM0123456789	9290	345	01V
	ASSA	Profile PM	PM0123456789	9291	345	01V
	ASSA	Profile PK	PK0123456789	9292	345	01V
	ASSA	Profile SH	SH0123456789	9293	345	01V
	BURG		D1001-3187	9294	1643	01V
	DOM 	Dom Plura	01234567	9295	3707	01V
	EURO LOCKS		2801-2900	9298	4081	01V
	L&F		W1001-3000	9299	4082	01V
	NEMEF		NF21234567890	9300	3481	01V
	NEMEF		NF11234567890	9301	3481	01V
	ANKER		FK1234567	9302	2888	01V

BUG FIXED



FUTURA PRO NEWS WEB



- Problem solved regarding copying a key with measurements read after decoding (Standard Keys system only).
- CISA code search for series:SN 1273.
- Solved a problem related to the cutting of "Vachette Radial VAC91" SN 76.
- Solved a problem related to the cutting of "Kia - Hyundai (4T-6W)" SN 1001, 1310.
- Solved a problem related to the cutting of GOAL: SN 547, 1182.
- Solved a problem related to the decoding of SN 1538 "RB-LOCKS Locxis".
- Problem solved regarding gauging/cutting/decoding for MAGNUM and M&C systems: SN 1540, 1523, 1524, 1525, 1526, 1527, 1528.
- Decodes for SN 1550.
- Solved a minor Software problem.

February 2016

1_2016 FUTURA v. 2.16.0

NEW SYSTEM

	Lock Manufacturer	Lock System	Profile/Series	SN	Card	Clamp
	ABUS	EC660	S00001A-S30000A	1668	4063	01R-05J-06J
	APECS	Premier CD (7+7)	-	1665	4056	01R-01J-02J
	BKS	WS50 - (Profile NW)	-	743	2228	01R-039J-038J
	DOM	IXGamma (Prf.153) (5+3+7)	-	1231	3189	01R-46J-45J
	DOM	IXGamma (Prf.155) (5+3+7)	-	1245	3191	01R-46J-45J
	HONDA	Honda Motorcycle (4T-6W)	A...101-800	1655	4036	01R-01J-02J
	HONDA	Honda Motorcycle (4T-6W)	B...101-800	1670	4036	01R-01J-02J
	GOAL	D-9 (3+3+3)	-	1669	4064	01R-01J-02J
	M&T	New Power (7W-2P)	2000002-2353872	1671	4067	01R-01J-02J
	STS	ST6 (6+5+11)	-	1131	2986	01R-58J-61J
	STS	ST8	-	1151	3006	01R-58J-61J
	BOMMER		1001-2000	9166	1039	01V
	ABUS	T12	TD 00001-02000	9266	3908	01V
	ABUS	T10	TE 00001-02000	9267	3908	01V
	CHICAGO		1E01-3E00	9268	1041	01V
	CHICAGO		1EY01-2EY00	9269	1041	01V
	CHICAGO		1GW1-3GW0	9270	1041	01V
	MEDECO	KeyMark X4	123456789	9271	4059	01V
	CHICAGO		DLP 0001-1742	9272	561	01V
	SENTRY		SB 1-9	9273	4061	01V
	TRIO-VING	R-key	123456789	9274	4062	01V
	ARCO		LG 3001-5999	9275	1040	01V
	ARCO		TG 3001-5999	9276	1040	01V
	ABUS	Abus V65	V65 1-331	9277	730	01V
	ABUS	Abus V63	V63 1-331	9278	730	01V
	KABA	Kaba Peaks A2 (0.150") (7P)	123456789	9279	1620	01V
	EURO LOCKS		T 2001-2200	9280	298	01V
	ERA		123456789	9281	2427	01V
	EURO LOCKS		E 1-200	9282	298	01V
	EURO LOCKS		N1-200R	9283	298	01V
	EBERHARD		U201-300	9284	4066	01V

BUG FIXED



FUTURA PRO NEWS WEB



Fixed data card data of SN 272-1475 (AGENT), 1267 (ALPHA), 547-731-884-1182 (GOAL), 1164-1268 (NAGASAWA), 613-1561 (SHOWA), 1065-1358 (TOSTEM), 477-638-639-1135-1471-1472-1476-1477 (WEST)

January 2016

1_2016 FUTURA v. 2.15.0

NEW SYSTEM

	Lock Manufacturer	Lock System	Profile/Series	SN	Card	Clamp
	Nissan	Emergency Key (5+5+4)	-	1658	4045	01R-01J-02J
	Wilka	P2	-	1660	4046	01R-48J-47J
	Wilka	PR300Q	-	1661	4048	01R-48J-47J
	Wilka	P3Q	-	1662	4049	01R-48J-47J
	Yale	2000 Plus Series (5+5)	ABC10001-AEH26822	1663	4050	01R-03J-02J
	MINDA-HUF		3001-3858	9222	4022	01V
	MINDA-HUF		1001-2252	9223	4037	01V
	MINDA-HUF		2001-3170	9224	4038	01V
	MINDA-HUF		1001-2174	9225	4039	01V
	BURG		1234	9226	4040	01V
	FORD	Market TAIWAN	12345	9227	4041	01V
	FEDERAL	YCF 35-35	6Y200001-298246	9228	4042	01V
	CHICAGO		5AH1-7AH5	9229	1041	01V
	ABUS	Abus V63	X631-331	9230	730	01V
	ABUS	Abus Z74	Z741-1043	9231	729	01V
	SOFICLEF	50/40	123456789	9232	4043	01V
	ILLINOIS		SD101-110	9233	4015	01V
	ILLINOIS		J200-703	9234	4015	01V
	JOFCO		J401-440	9235	1054	01V
	NATIONAL		RD001-615	9236	1054	01V
	NATIONAL		PA001-634	9237	1054	01V
	NATIONAL		PG001-575	9238	1054	01V
	MAZDA	Market TAIWAN	1234	9239	4044	01V
	NATIONAL		C001-175B	9240	1054	01V
	NATIONAL		GF201-400	9241	1054	01V
	GUARD	Profile G17	17T1500000-99999	9242	666	01V
	NATIONAL		D001-633AR	9243	1054	01V
	NATIONAL		B001-633A	9244	1054	01V
	NATIONAL		C001-633A	9245	1054	01V
	NATIONAL		D001-633A	9246	1054	01V
	NATIONAL		FF001-574	9247	1054	01V
	CHICAGO		5D66-6D30	9248	1041	01V
	CHICAGO		1X01-3X00	9249	1041	01V
	CHICAGO		1X1-7X6	9250	1041	01V
	CHICAGO		1MC1-6MC5	9251	1041	01V



FUTURA PRO NEWS WEB



CHICAGO		1BM01-2BM00	9252	1041	01V
CHICAGO		1MS1-3MS1	9253	1041	01V
CHICAGO		1RR01-2RR00	9254	1041	01V
CHICAGO		1L001-450	9255	1041	01V
CHICAGO		2Y01-9Y99	9256	1041	01V
CHICAGO		2HM01-5HM00	9257	1041	01V
CHICAGO		1B01-3B50	9258	1041	01V
CHICAGO		2K01-2K99	9259	1041	01V
CHICAGO		1N01-9N99	9260	1041	01V
CHICAGO		5D01-5D65	9261	1041	01V
CHICAGO		IS01-99	9262	1041	01V
PUNDRA		B0001-1092	9263	4018	01V
PUNDRA		K0001-1092	9264	4018	01V
HUWIL		14101-16020IG	9265	539	01V
CRAFTSMAN		Z8001-9000	9205	4017	01V

BUG FIXED



- Standard decoding refreshed for KESO: SN 57-273-673-1158-1298-1299-1576-1656-1657. systems



FUTURA PRO NEWS WEB



December 2015

1_2015 FUTURA v. 2.14.0

NEW SYSTEM

Lock Manufacturer	Lock System	Profile/Series	SN	Card	Clamp
Abus 	Bravus 1000 (Tip stop)	-	1646	4010	01R-29J-30J
Abus 	Bravus 2000 (Tip stop)	-	1650	4023	01R-29J-30J
Abus 	Bravus 4000 (Tip stop)	-	1654	4024	01R-29J-30J
Fort	CH10T (7P)	X01001-08704	1648	4020	02R
Kale	164 DBNE (5+5)	-	1643	2244	01R-01J-02J
Oxloc 	O9	-	1647	4014	01R-29J-30J
Pacri	Pacri (5+5)	-	1642	3981	01R-01J-02J
Anderson Hickey		NM01-NM128	9190	4009	01V
Bauer		BR500-BR999	9191	1069	01V
Chicago		H1001-3000	9192	1041	01V
Chicago		H2001-H2576	9204	4016	01V
Corbin		HB1-HB700	9193	1367	01V
Craftsman		LL151W-LL175W	9217	1288	01V
Craftsman		LL1W-LL225W	9108	1268	01V
Craftsman		3001-3050	9218	1268	01V
Craftsman		135	9205	4017	01V
Eagle		76P1-76P240	9194	1045	01V
Eagle		C1-C12	9195	1046	01V
F.I.C.		HF301-HF351	9201	4013	01V
Fastec		EF301-EF351	9199	4013	01V
Fastec		301-351	9198	4013	01V
Fastec		CF301-CF351	9200	4013	01V
Fort		X01001-X08704	1648	4020	01V
Haworth		HW001-HW300	9197	4011	01V
Ilco		C26-C50	9196	1049	01V
Illinois		H200-H483	9202	4015	01V
National		HBH1250-HBH1749	9179	4030	01V
National		AM1-AM950	9189	1043	01V
National		1N-400N	9187	1043	01V
National		D100-D7000	9186	1043	01V
National		1-970	9180	1043	01V
National		RN601-RN791	9188	1043	01V
Pundra		S1-S1092	9206	4018	01V
Sentry		3A2-3K2	9207	4019	01V
Taylor		B101-B112	9135	1062	01V
Taylor		F10-F21	9136	1063	01V
US Lock		123456789	9203	4012	01V
Subaru		32000--39867	8816	3646	01V
Subaru		50000-69999	9208	3646	01V
Bommer		0123456	9166	1039	01V
Honda		000-1013	8939	3806	01V
Miwa	Market Jap side A	123456	9167	3970	01V
Miwa	Market Jap.side A	123456	9168	3972	01V
Miwa	Market Japan.	1234	9171	3975	01V
Mitsubishi	Market Jap. stop 3	8100-9113	9169	3973	01V
Squire&Sons	ATL4 & ATL5	123456789	9172	3976	01V
Squire&Sons	KB	123456789	9173	3979	01V
Eurolocks		12345	9174	3982	01V



FUTURA PRO NEWS WEB



	Toyota	Chinese market (reversed cuts)	1234	9176	3985	01V
	Ronis		12345	9175	3984	01V
	Minda-Huf		A1001-3500	9177	3987	01V
	Honda		R/S0001-1074	9178	4003	01V
	Ifam	E-50-60-70 & M-50-60	123456	9214	4029	01V
	Ifam		123	9211	4028	01V
	Ifam		123456	9212	4027	01V
	Ifam		123456	9213	4027	01V
	Ifam	E-30 & M-30		9210	4025	01V
	Ifam	E-40 & M-40		9215	4025	01V
	Hyundai	Chinese market	M0001-2500	9209	3419	01V
	Hyundai	KIA (DEPTHS 1-5)	V0001-2500	9216	3419	01V
	Oxloc	Oxloc O8		9185	4007	01V
	Oxloc	Oxloc O7		9181	4006	01V
	Oxloc	Oxloc O7		9182	4006	01V
	Oxloc	Oxloc O7		9183	4006	01V
	Oxloc	Oxloc O7		9184	4006	01V
	Craftsman		LL151-175W	9217	1268	01V
	Winkhaus	W-Profile		9219	4033	01V
	Winkhaus	XL-Profile		9220	4034	01V

BUG FIXED



- Solved a problem related to the cutting of DOM: SN 861-862-1027-1244.
- Solved some problem about “**User code table import**”.
- Solved a problem related to the decoding of SN 1269 “Sanwa (2+1+2+1+1+1P)”.



FUTURA PRO NEWS WEB



November 2015

1_2015

FUTURA v. 2.13.3

BUG FIXED



- Solved a minor Software problem.

November 2015

1_2015

FUTURA v. 2.13.2

BUG FIXED



- Solved a problem related to the decoding of SN 1348 "BMW BW9EHP (4T-4W)".
- Solved a problem related to the cutting of "Bmw (2T-8W)" SN 1572 .

November 2015

1_2015

FUTURA v. 2.13.1

BUG FIXED



- Standard decoding refreshed for DOM systems.



FUTURA PRO NEWS WEB



October 2015

1_2015 FUTURA v. 2.13.0

REMEMBER TO



- Remember to update the Silca.apk and SilcaKeyboard.apk after installing the Software update (see the on board Instructions Manual - Ch 7.3 APP UPDATE (APK))
- With the new **MySilca apk** from Silca, you can keep the entire expertise and experience of your Key Partner at hand anytime anywhere.

NEW SYSTEM



Lock Manufacturer	Lock System	Profile/Series	SN	Card	Clamp
Corbin	Corbin TWO (6P)	-	1615	1500	01R-01J-02J
Tokai Rika	Subaru Emergency Key (2T-4W)	-	1635	3964	01R-01J-02J
Union	Union EG	123456	9165	4593	01V

NEW FUNCTIONS



- As an alternative to a tablet ↔ machine Wi-Fi connection, a USB connection can be used with the cable provided. To activate this connection enable the Android **“Tethering USB” function from the Settings menu on the Android tablet** (see User's Manual version 7).
- The Futura machine can be registered through any browser, at the web address <https://www.silcawebsw.biz/futura/reg/index.html>
- Silca periodically distributes Software and Data updates for FUTURA. A message will occasionally notify you to check for new updates using one of the connection modes available (see menu Options -> Updates).
- Decodes for SN 1228 and 1229

BUG FIXED



- Standard decoding refreshed for KESO systems: SN 20-21-105-807
- Problem solved relating to saving the “Wi-Fi channel” setting (if different from default) after a software update
- Solved a problem related to the cutting algorithm of “Standard Key” (method “M_LASER_FLAT_LFD”).

September 2015

1_2015 FUTURA v. 2.12.0

REMEMBER TO



- Remember to update the Silca.apk and SilcaKeyboard.apk after installing the Software update (see the on board Instructions Manual – Ch 7.3 APP UPDATE (APK))
- With the new **MySilca apk** from Silca, you can keep the entire expertise and experience of your Key Partner at hand anytime anywhere.

NEW SYSTEM



Lock Manufacturer	Lock System	Profile/Series	SN	Card	Clamp
Avocet	Avocet Pioneer plus (6P)	-	1612	3936	01R-01J-02J
Prefer	Prefer S211 (5+5+4)	-	1633	3942	01R-01J-02J
Prefer	Prefer UL20 (6P)	-	1463	3715	01R-01J-02J
Prefer	Prefer W551 (4+4+3)	-	1632	3941	01R-01J-02J
Trelock	Trelock RS430 (4T-7W)	H400000-404999	1556	3865	01R-01J-02J
Ankerslot		EE112-545	9159	3431	01V
Burg		18001-18246	9162	1643	01V
Euro Locks		H1001-3000	9161	723	01V
Euro Locks		G1001-3000	9160	723	01V
Euro Locks		F4001-5000	9163	1435	01V
JPM		12345678	9157	3935	01V
Marutti Suzuki		IP5001-6001	9158	3937	01V

NEW FUNCTIONS



- New **“Transponder Guide”** function accessible from the Search menu. This function contains all the transponder key copying solutions provided by Silca.
- Use of Silca Remote Service (SRS) Version 1.0.38.5** to register your Futura machine on the Silca server.
- Use of Silca Remote Service (SRS) Version 1.0.38.5** to update your Futura machine in one of the ways described below:
 - **Quick update** (saves time as only the files needed for updating are downloaded onto a blank FAT32 format USB PEN)
 - **Total update** (all the files related to updating are downloaded onto a blank FAT32 format USB PEN)

** The program can be downloaded from the Silca website **www.silca.biz**; select the Products menu -> Silca Key Programs -> SKP Forms -> Silca Remote Service



FUTURA PRO NEWS WEB



BUG FIXED



- Solved a problem related to the decoding of SN 1285 Euro Locks (2T-5W).
- Solved a problem related to the cutting of HONDA: SN 582-619-805-806
- Solved a problem related to the cutting of KESO: SN 20-273-1299

July 2015

1_2015 FUTURA v. 2.11.3

NEW SYSTEM



Lock Manufacturer	Lock System	Profile/Series	SN	Card	Clamp
Cisa	Cisa AP3 DA/CA/CE	XN.0161.10	734	1600	01R-05J-06J
Cisa	Cisa Asix Pro (6P)	00012-38832 DC	1607	1575	01R-05J-06J
Cisa	C3000	(XN029010) 000001-238428	9156	3928	01V
Cisa		AT..... 00001-03628	7774	5590	01V
Cisa	C2000 5P 0,44	AR..... 00001-20728	8490	2183	01V
Cisa	C2000 5P 0,65	AR..... 00001-20728	8488	2182	01V

July 2015

1_2015 FUTURA v. 2.11.2

BUG FIXED



- Solved a problem related to the cutting algorithm of (Standard Key)

July 2015

1_2015 FUTURA v. 2.11.1

BUG FIXED



- Fixed a problem related to cutting PFAFFENHAIN (Vitess-Zolit)

June 2015

1_2015 FUTURA v. 2.11.0

REMEMBER TO



- **Remember** to update the Silca.apk and SilcaKeyboard.apk after installing the Software update (see the on board Instructions Manual – Ch APP UPDATE (APK)).
- With the new **MySilca apk** from Silca, you can keep the entire expertise and experience of your Key Partner at hand anytime anywhere.

NEW SYSTEM

	Lock Manufacturer	Lock System	Profile/Series	SN	Card	Clamp
	Yale	Yale 1000 Series (6P)	40001-53260	1592	3448	01R-13J-02J
	Iseo	Iseo R7 (5+6)	EDL000001-350589	916	2176	01R-01J-02J
	Pfaffenhain	Pfaffenhain Vitess 2000 (4P)	-	1598	3914	01R-28J-25J
	Pfaffenhain	Pfaffenhain Vitess 4000 (4P)	-	1599	3918	01R-28J-25J
	Pfaffenhain	Pfaffenhain Zolit 2000 (4P)	-	1600	3919	01R-24J-25J
	Pfaffenhain	Pfaffenhain Zolit 4000 (4P)	-	1601	3920	01R-24J-25J
	Brisant	Brisant ULTION (5+6)	U11000001-11291140	1605	3925	01R-01J-02J
	Hyundai	Hyundai (4T - 6W)	LK....0001-2500	1580	2372	01R-01J-02J
	Hyundai	Hyundai (4T - 6W)	M....0001-2500	1581	2372	01R-01J-02J
	Kia	Kia (4T - 6W)	E....0001-2500	1582	2372	01R-01J-02J
	Hyundai	Hyundai (4T - 6W)	HK....0001-2500	1583	2372	01R-01J-02J
	Kia	Kia - (4T-6W)	KG....0001-2500	1584	2372	01R-01J-02J
	Kia	Kia (4T - 6W)	V....0001-2500	1585	2372	01R-01J-02J
	Hyundai/Kia	Kia-Hyundai (4T-6W)	K....0001-2500	1586	2372	01R-01J-02J
	Hyundai	Hyundai (2T-8W)	1001-3500	1587	3336	01R-01J-02J
	Hyundai	Hyundai (2T-8W)	X....1001-3500	1588	3336	01R-01J-02J
	Kia	Kia (4T - 5W)	KU....0001-2608	1589	3742	01R-01J-02J
	Hyundai	Hyundai (4T - 5W)	B....0001-2608	1590	3742	01R-01J-02J
	Kia	Kia (2T-8W)	UM....1001-3500	1591	3618	01R-01J-02J
	Hyundai	Hyundai (4T - 5W)	X....0001-2254	1596	3909	01R-01J-02J
	Hyundai	Hyundai Card Key (2T - 5W)	X....0001-2254	1597	3911	01R-01J-02J
	Zadi/Giussani/Ft	Giussani (2T-8W)	-	1603	3924	01R-01J-02J
	Huf	Mercedes HU64P (2T-10W)	-	1602	3921	01R-01J-04J
	Dom	DORMA RS-8 SINGLE CODED	UK 15000-23971	9154	2990	05V
	Dom	DORMA RS-8 SINGLE CODED	UK 01001-14047	9155	2990	05V
	Abus	E50	12345	9147	3908	01V
	Pfaffenhain	Vitess 2000	9876543210XYZ	9146	3907	04V
	Pfaffenhain	Zolit 1000	9876543210XYZ	9148	3910	01V
	Pfaffenhain	Vitess 1000	9876543210XYZ	9149	3913	04V
	Pfaffenhain	Zolit 2000	9876543210	9150	3915	01V
	Pfaffenhain	Zolit 4000	9876543210XYZ	9151	3916	01V
	Pfaffenhain	Vitess 4000	9876543210XYZ	9153	3922	04V
	Federal	Avocet ATK	012345678	9152	3917	01V



FUTURA PRO NEWS WEB



NEW FUNCTION



- Decodes for SN 823, 850 and 860 (Renault, Peugeot, Citroen and Toyota car keys)
- SMART decoding for KESO 1000-2000-4000-CASA systems. The new decoding recognises the real key cuts and ignores "PRE-CUTS" (cuts by manufacturer).

BUG FIXED



- Fixed a problem related to cutting DOM: SN 861-862-1027-1244.



FUTURA PRO NEWS WEB



May 2015

1_2015 FUTURA v. 2.10.0

REMEMBER TO



- **Remember** to update the Silca.apk and SilcaKeyboard.apk after installing the Software update (see the on board Instructions Manual – Ch APP UPDATE (APK)).
- With the new **MySilca apk** from Silca, you can keep the entire expertise and experience of your Key Partner at hand anytime anywhere.

NEW SYSTEM

	NEW SYSTEM					
	Lock Manufacturer	Lock System	Profile/Series	SN	Card	Clamp
	Honda	Honda Emergency Key (2T-6W)	-	3896	1575	01R-52J-53J
	Spider	SPIDER (5+5+5)	-	165	876	01R-01J-02J
	Chairo	CHAIRO 118 (6P)	-	1570	3889	01R-01J-02J
	Duro	DURO 280/50 (6+6)	-	1571	3892	01R-01J-02J
	Lince	Lince XA, XB,	-	1834	683	01R-24J-25J
	Keso	Keso Casa	-	1576	3898	01R-01J-02J
	Huf	Bmw (2T-8W)	-	1572	3893	01R-01J-02J
	Dom	Dom IXDAS (Prof.138) (5P)	-	861	2457	01R-01J-02J
	Dom	Dom IXDAS (Prof.138) (5+6+6)	-	862	2458	01R-01J-02J
	Dom	Dom IXDAS (Prof.138) (Precoded key only)	-	1027	2744	01R-01J-02J
	Dom	Dom IXGamma (Prf.154) (5+3+7)	-	1244	3190	01R-46J-45J
	Mauer	Mauer_NW4 (5P - 2T-5W)	-000101-651630	1264	3897	01R-54J-55J
	Ces	Ces WSM NEW (5+5+6)	-	1495	3767	01R-01J-02J
	Chicago		FR301-800	9102	561	01V
	National Rockford		T1-675	9103	1043	01V
	Sargent	DG1	123456	9104	3890	01V
	Sargent	DG2-DG3	123456	9105	3891	01V
	Piaggio Cycles		1001-3532	9106	258	01V
	Avocet	ATK	012345678	9107	3899	01V
	Weslock		01234567	9145	3900	01V



FUTURA PRO NEWS WEB



NEW FUNCTION



- New “User code table import” function accessible from “Settings”=> “User series”. This new function allows users to import a code table in the XML-Keso or csv format to create a new user series
- New “Change dimensions” function. For all edge symmetrical keys, it is now possible to view dimensions in two ways: Depths referred to the middle of the key or depths referred to the edge of the key
- Improved the “Queue of jobs.” function

BUG FIXED



- Solved some problems related to machine software updating via tablet. For more details refer to the user manual (version 5.0 section 6.2.3)

May 2014

1_2015 FUTURA v. 2.9.1

BUG FIXED



- Solved the problem of password enabling for some data cards (Futura NA)



FUTURA PRO NEWS WEB



March 2015

1_2014 FUTURA v. 2.9.0

REMEMBER TO



- **Remember** to update the Silca.apk and SilcaKeyboard.apk after installing the Software update (see the on board Instructions Manual – Ch 6.2 APP UPDATE (APK)).
- With the new **MySilca apk** from Silca, you can keep the entire expertise and experience of your Key Partner at hand anytime anywhere.

NEW SYSTEM



Data update with new main series.

- | | |
|-------------------------------------|---|
| ■ Agent BJ-1(5+5+5) | ■ Ezcurra DS10/15 (5+5) |
| ■ BKS WS42 - WS50 MK | ■ EUROSPEC MPX6Plus |
| ■ Bunka (Market Japanese) | ■ FCV (6P) - (6+5+4) |
| ■ Ces UDM (4P) - WSM NEW (5+5+6) | ■ Giobert Alfa Romeo GT2AP (5+5) - Lancia GT2 (5+5) |
| ■ Dom (Dom RS8) | ■ Goal AD5 (Market Japanese) |
| ■ Dom IX5 DAS (pf.038/101) | ■ Honda (Market India) |
| ■ Dom IX6 SR E (prof 232) | ■ Iseo R7 Extra |
| ■ Dom IX6 SR E (prof 233) | ■ Metal X6S - X6V (Market Bulgarian) |
| ■ Dom IX6KG (Prof.102) (5+5+5) | ■ Mg HS Plus (5+5+5) |
| ■ Dom IX6SR E (prof. 230) | ■ Schlage Everest SFIC |
| ■ Dom IX6SR E (prof. 235) | ■ Showa W2-DAC (4T-4W) |
| ■ Dom IX6SR E (prof.129/130/241) MK | ■ Snc – 30/30 (Market Bulgarian) |
| ■ Dom IX6SR E (prof.131/132/233) MK | ■ Titan T200 |
| ■ Dom IX6SR E (prof.232/234) AT | ■ Wilka PR300 |
| ■ Dorma 2 in 1 (Prof. 233) (5P) | ■ Wilka Carat - P3 |
| | ■ Wilka Carat - P1 |
| | ■ Wilka PR100 |
| | ■ Yamaha (Market India) |

NEW FUNCTION



- New Function "Cutting Tree" from "Card => Partial cuts". This function shows you how to recut multiple codes onto the same key blank so you can test each one and use a minimum number of key blanks.
- New Function "Cutting speed tuning" on Copy by original, copy by card for standard, laser and dimple keys. Using this function, it's possible to change the "cutting speed" and the "Depth removal step" according to the thickness and the material of the blank key to be cut.
- Turkish language.



FUTURA PRO NEWS WEB



February 2015

1_2014 FUTURA v. 2.8.0

REMEMBER TO



- **Remember** to update the Silca.apk after installing the Software update (see the on board Instructions Manual – Ch 6.2 APP UPDATE (APK)).
- With the new **MySilca App** from Silca, you can keep the entire expertise and experience of your Key Partner at hand anytime anywhere.

NEW SYSTEM



Data update with new main series.

- Honda (Market India)
- Honda (4T-6W)
- Keso 2000 S (Special)
- Metal (X6V)
- Metal 2x6J 30/30 (6P)
- Trio-Ving (Triton)
- Viro Palladium (7P)
- Viro Palladium PV (7P)
- Yale YA35/40 MSG SN
- Yamaha (Market India)

BUG FIXED



- Fixed a problem related to cutting more than one piece for some systems
- Fixed a problem related to cutting and decoding of card 1493 (Keso 1000)

February 2015

1_2014 FUTURA v. 2.7.1

BUG FIXED



- Fixed a problem related to searching by Sn



FUTURA PRO NEWS WEB



February 2015

1_2014 FUTURA v. 2.7.0

REMEMBER TO



- **Remember** to update the Silca.apk after installing the Software update (see the on board Instructions Manual – Ch 6.2 APP UPDATE (APK)).
- With the new **MySilca App** from Silca, you can keep the entire expertise and experience of your Key Partner at hand anytime anywhere.

NEW SYSTEM



Data update with new main series.

- | | |
|---------------------|-----------------|
| ■ Brisant (6P) | ■ Metal (x6s) |
| ■ Cisa (CS501) | ■ Snc (30/30) |
| ■ Gege (pExtra Swe) | ■ Valeo (2T-8W) |

BUG FIXED



- Fixed a problem related to cutting/decoding of MAGNUM : SN 1524, 1525, 1527, 1528.
- Fixed a problem related to the cut algorithm of SEA : SN 34-35.
- Fixed a problem related to the cut algorithm of VALEO : SN 1117.



FUTURA PRO NEWS WEB



January 2015

1_2014 FUTURA v. 2.6.1

BUG FIXED



- Fixed a problem related to German language

January 2015

1_2014 FUTURA v. 2.6.0

REMEMBER TO



- Remember** to update the Silca.apk and SilcaKeyboard.apk after installing the Software update (see the on board Instructions Manual – Ch 6.2 APP UPDATE (APK)).
- With the new **MySilca App** from Silca, you can keep the entire expertise and experience of your Key Partner at hand anytime anywhere.

NEW SYSTEM

Data update with new main series.

- ABUS (System V14-XY14-Y14 - Abus Bravus 1000-2000-3000-4000)
- ANKERSLOT (Infinity / Multi)
- ASSA_NEP (Neptun)
- ASSA_TRI (Triton 5900 - P600)
- ATRA / DIERRE (Atra New Power (7W-2P) – Padronale)
- CES (CES PSM-UDM)
- CISA/ABUS (SP-TSP)
- DOM (Dom-Sigma - System RN (5P/6P))
- EURO LOCKS (Euro Locks MK U (2T - 10W))
- GEGE (APN-ESP-AP-CNS - pExtra-ANS-2-3-4)
- GERA (Gera 2000 Plus)

- GTV (Standard GTV)
- ISEO (Iseo KLE8R (5+5))
- KABA (Kaba maTriX (K59))
- KESO Keso 1000/Lips (3A)
- MAGNUM (Magnum Superior/Superior+)
- MAUER (Mauer DT-1)
- MLS / MAUER (MAUER ML+ (5+5))
- PFÄFFENHAIN (Pfaffenhain Wavy line Pro - Pfaffenhain KV14 - XV14 - Pfaffenhain Integral 14)
- RUKO (Merkur 401)
- VACHETTE (Radial)
- WILKA (Carat-P1-PR100-P1)
- WINKHAUS (AZ/RPE/RPS/VS/VS6/Xpert - TEC RPS/RPE)

NEW FUNCTION



- If Futura is not connected to Internet, it is now possible to download the Futura Software update into the tablet connected to internet and then upgrade the machine from the tablet.
- If Futura is not connected to internet, it is now possible to download the software upgrade **into the PC via Silca Remote Service (SRS)** and then use a USB PEN to



FUTURA PRO NEWS WEB



upload the Upgrade to the machine.

- If requested **register the machine to Silca Web**, in order to join the 6 months Free Subscription.

BUG FIXED



- Fixed a problem related to decoding of Serial Number 1255 ISEO CSR R9 PLUS N.
- Fixed data card data of SN 34, 35, 628, 929, 1117, 1285.
- Fixed a problem related to cutting cards 3207 and 3769 after decoding.



FUTURA PRO NEWS WEB



November 2014

1_2014

FUTURA v. 2.5.0

BUG FIXED



- Improved the "Connect to" function that allows to easily find the Futura IP address in a network accessible via router.
- Solved a problem related to the decoding of dimple keys that in some instances returned a wrong combination
- Solved a problem related to the cutting of dimple keys following decoding
- Solved a problem related to the decoding of edge keys with depths lesser then 4.10 mm
- Solved a problem related to the cutting algorithm of Esety Omega (card 2211)
- Solved a problem related to the cutting algorithm of Abus EC550 (card 2749)
- Solved the problem of white screen on tablet following some searching operations
- Fixed the displaying of ILCO references
- Restored card 2549 (Atra New Power) erroneously eliminated in the previous version

November 2014

1_2014

FUTURA v. 2.4.3

BUG FIXED



- Solved the problem related clamp 02V

November 2014

1_2014

FUTURA v. 2.4.1

BUG FIXED



- Solved a minor Software problem



FUTURA PRO NEWS WEB



October 2014

1_2014

FUTURA v. 2.4.0

NEW SYSTEM



Data update with new series.

- Russwin (A Class-old – 981 Class- 752 Class)
- Best (A3)
- YAMAHA (Market India)
- Atra New Power (7W-2P)

October 2014

1_2014

FUTURA v. 2.3.0

NEW SYSTEM



Data update with new series.

- HERO HONDA (Market India)
- BAJAJ (Market India)
- MAHINDRA (Market India)



FUTURA PRO NEWS WEB



September 2014

1_2014 FUTURA v. 2.2.0

NEW SYSTEM

Data update with new series.



- AVOCET (Avocet ABS)
- CES (Ces WSM (5+5+6))
- DOM (Dom IX Emergency- Dom IX Hochrippe (5+5+5))
- KABA (Kaba K6 (K6)- Kaba K8 green (K8G) (4+4+4)- Kaba K8S (K14))
- LOB (Lob Nefryt (5P))
- MOTTURA (Mottura C28 (5+4+4)- Mottura C30-C31 (5+4))
- PFAFFENHAIN (Pfaffenhain Wavy line)
- TITAN (K66)
- MIWA (Miwa UR- Miwa U9)
- GUARD (Profile G11-G12-G13- G14- G17- EPS/P EP83)
- MUL.T.LOCK (Mul.T.Lock Interactive (115)- (115) MK- (206)- (215)- (225)- (262)- (264)- Mul-T-Lock MT5)

NEW FUNCTION



- CISA code search for series: (SN 631-634-635-733)
- A new function that allows third party programs (such as Master Key Program) to transmit a job to the Futura "Queue of jobs" using a wireless connection or a local area network
- Japanese language

BUG FIXED



- Fixed a problem related to an OPEN router connection (without password)



FUTURA PRO NEWS WEB



June 2014

1_2014 FUTURA v. 2.1.10

BUG FIXED



- Solved the problem of the message "Internal Server Error" after the update, if it has been selected in the machine the Measurement unit "Thousandths of Inch"

June 2014

1_2014 FUTURA v. 2.1.8

NEW SYSTEM



Data update with new series.

- | | |
|-----------------------------------|--------------------------------|
| ■ GERDA (WKM3; WKM1) | ■ AGB (5000) |
| ■ CORBIN (Evolution) | ■ GERA (WS; WSG; 2000 Plus) |
| ■ LINCE (C4;C2) | ■ IFAM |
| ■ MAUER (MLS) | ■ VIRO |
| ■ ISEO (CSR R9 Country N; Plus N) | ■ MOTTURA (C43) |
| ■ TESA | ■ BASI (CX6 Left) |
| ■ KESO (2000S;4000S) | ■ ESETY (Omega) |
| ■ KABA (Titan; 8S-14 Mixed) | ■ ANKERSLOT (Infinity / Multi) |
| ■ YALE | ■ HUGO (GR 2.55) |
| ■ ABUS (NW52;NW72) | |

NEW FUNCTION



- Decoding and copying using read measurements
- Management of more jaws for the same data card

BUG FIXED



- Corrected a decoding problem related to some dimple keys
- Solved the problem related to search of some data card



FUTURA PRO NEWS WEB



May 2014

1_2014

FUTURA v. 2.0.1

BUG FIXED



- Solved the problem of password enabling for some data cards

May 2014

1_2014

FUTURA v. 2.0.0

NEW FUNCTION



- Management of comparatives and alternatives key
- Option to select the key manufacturer
- Option to detect key blank measurement before cutting edge keys

BUG FIXED



- Copy a SIMPLEX Key by card
- Error in decoding dimple key due to a false electric contact.
- Improved accuracy and performance of "Copy by original"