Fassa Wall Folie



$CE-Safety\ data\ sheet\ according\ to\ norm\ 91/155/CE$

REV1--28/08/12

1. Identification	
· Product (Name)	Fassa Wall Folie
· Supplier	Façabelle Industriepark 20 (zone B) B-2220 Heist-op-den-Berg BELGIUM
 Type of raw material Telephone number of urgent call to Façabelle Most important use 	 Polyethylene, Polypropylene Tel. +32 (0)15 73 07 42 waterproofing
2. Composition/information	 Polyethylene approximately 65% CAS: 9002-88-4 Polypropylene approximately 35% CAS: 9003-07-0
3. Danger	 Inhalation: At temperatures higher than 200 °C it can create smoke which can irritate the respiratory system, causing coughing and loss of breath. Skin contact: Contact with the hot or molten product can provoke severe burns. Physical and chemical danger: Combustible if exposed to fire. Friction of the product creates an electrostatic charge. Sparks can cause fire or a dust explosion at certain concentrations.
4. First aid	 Inhalation: Exposure to smoke and vapour of hot or burnt product. In case of asphyxia or illness caused by exposure to smoke, remove the person immediately to the open air. If necessary call a doctor. Skin contact Contact with hot or molten material: Cool immediately the affected area with running cold water DO NOT try to remove the polymer from the skin. Generally it will detach itself after a few days. In case of extremely severe burns call a doctor immediately Contact with the eyes: Cool the affected area immediately with running cold water Cool immediately the eyes with cold water Take the person immediately to hospital Specials treatment may be required.

Extinguishers recommended: For small fires use powder extinguishers, CO2 extinguishers or water. For serious fires: foam, vaporized water to cool down surfaces exposed to the fire. Prohibited extinguishers: NEVER use high pressure water jets at the beginning; as this could increase the spread of flames. Combustion risks: Avoid smoke inhalation. Protection measures: Wear protective masks. 6. Measures to be adopted in case of accidental spread: Invironmental precautions: Remove naked flares and any possible sources of combustion. Do not smoke. If the product has gone into a river, sewer or it has polluted either the ground, or vegetation, the authorities must be informed. Cleaning methods: Collect the product for re-cycling, if possible, or to dispose of it. Handling and storage: Handling precautions: Do not smoke during installation. Storage: Keep away from naked flames, sparks and heat sources. Precautionary measures: None. 9. Physical/chemical features: Appearance and colour: blue Odour: none Flash point: 340 °C Density at 20 °C: from 900 to 990 Kg/m3 10. Stability and reactivity: Substances to be avoided: Stable under normal conditions. Substances to be avoided:
water. For serious fires: foam, vaporized water to cool down surfaces exposed to the fire. Prohibited extinguishers: NEVER use high pressure water jets at the beginning; as this could increase the spread of flames Combustion risks: Avoid smoke inhalation Protection measures: Wear protective masks. 6. Measures to be adopted in case of accidental spread: Remove naked flares and any possible sources of combustion. Do not smoke. If the product has gone into a river, sewer or it has polluted either the ground, or vegetation, the authorities must be informed Cleaning methods: Collect the product for re-cycling, if possible, or to dispose of it. 7. Handling and storage: Handling precautions: Do not smoke during installation Storage: Keep away from naked flames, sparks and heat sources. Precautionary measures: None. 9. Physical/chemical features: Appearance and colour: Do not smoke during installation Storage: Storage: Appearance and colour: Do not smoke during installation Storage: Storage: Appearance and colour: Do not smoke during installation Storage: Storage: Appearance and colour: Do not smoke during installation Storage: Storage: Appearance and colour: Do not smoke during installation Storage: Storage: Appearance and colour: Do not smoke during installation Storage: Storage: Appearance and colour: Do not smoke during installation Storage: Storage: Appearance and colour: Do not smoke during installation Storage: Storage: Appearance and colour: Do not smoke during installation Storage: Appearance and colour: Do not smoke during installation Storage: Appearance and colour: Do not smoke during installation Storage: Appearance and colour: Do not smoke during installation Storage: Appearance and colour: Do not smoke during installation Storage: Appearance and colour: Do not smoke during installation Storage: Appearance and colour: Do not smoke during installation Storage: Appearance and colour: Appearance and colour: Appearance and colour: Appearance and c
For serious fires : foam, vaporized water to cool down surfaces exposed to the fire. Prohibited extinguishers: NEVER use high pressure water jets at the beginning; as this could increase the spread of flames Combustion risks : Avoid smoke inhalation Protection measures: Wear protective masks. 6. Measures to be adopted in case of accidental spread: In the product precautions: Remove naked flares and any possible sources of combustion. Do not smoke. If the product has gone into a river, sewer or it has polluted either the ground, or vegetation, the authorities must be informed Cleaning methods: Collect the product for re-cycling, if possible, or to dispose of it. 7. Handling and storage: I Handling precautions: Do not smoke during installation Storage: Keep away from naked flames, sparks and heat sources. 8. Control on exposure / personal protection: Precautionary measures: None. 9. Physical/chemical features: Appearance and colour: Density at 20°C: Density at 20°C: from 900 to 990 Kg/m3 10. Stability and reactivity: Stable under normal conditions.
exposed to the fire. Prohibited extinguishers: NEVER use high pressure water jets at the beginning; as this could increase the spread of flames. Combustion risks: Avoid smoke inhalation. Protection measures: Wear protective masks. 6. Measures to be adopted in case of accidental spread: Remove naked flares and any possible sources of combustion. Do not smoke. If the product has gone into a river, sewer or it has polluted either the ground, or vegetation, the authorities must be informed. Cleaning methods: Collect the product for re-cycling, if possible, or to dispose of it. 7. Handling and storage: Handling precautions: Do not smoke during installation. Storage: Keep away from naked flames, sparks and heat sources. 8. Control on exposure / personal protection: Precautionary measures: None. 9. Physical/chemical features: Appearance and colour: blue Odour:
exposed to the fire. Prohibited extinguishers: NEVER use high pressure water jets at the beginning; as this could increase the spread of flames. Combustion risks: Avoid smoke inhalation. Protection measures: Wear protective masks. 6. Measures to be adopted in case of accidental spread: Remove naked flares and any possible sources of combustion. Do not smoke. If the product has gone into a river, sewer or it has polluted either the ground, or vegetation, the authorities must be informed. Cleaning methods: Collect the product for re-cycling, if possible, or to dispose of it. 7. Handling and storage: Handling precautions: Do not smoke during installation. Storage: Keep away from naked flames, sparks and heat sources. 8. Control on exposure / personal protection: Precautionary measures: None. 9. Physical/chemical features: Appearance and colour: blue Odour:
Prohibited extinguishers: NEVER use high pressure water jets at the beginning; as this could increase the spread of flames. Combustion risks: Avoid smoke inhalation. Protection measures: Wear protective masks. 6. Measures to be adopted in case of accidental spread: Environmental precautions: Remove naked flares and any possible sources of combustion. Do not smoke. If the product has gone into a river, sewer or it has polluted either the ground, or vegetation, the authorities must be informed. Cleaning methods: Collect the product for re-cycling, if possible, or to dispose of it. 7. Handling and storage: Non smoke during installation. Storage: Keep away from naked flames, sparks and heat sources. Precautionary measures: None. 9. Physical/chemical features: Appearance and colour: blue Odour: Odour: none Flash point: 340 °C Density at 20°C: from 900 to 990 Kg/m3 10. Stability and reactivity: Stable under normal conditions.
NEVER use high pressure water jets at the beginning; as this could increase the spread of flames. Combustion risks: Avoid smoke inhalation. Protection measures: Wear protective masks. 6. Measures to be adopted in case of accidental spread: Remove naked flares and any possible sources of combustion. Do not smoke. If the product has gone into a river, sewer or it has polluted either the ground, or vegetation, the authorities must be informed. Cleaning methods: Collect the product for re-cycling, if possible, or to dispose of it. 7. Handling and storage: Handling precautions: Do not smoke during installation. Storage: Keep away from naked flames, sparks and heat sources. Precautionary measures: None. 9. Physical/chemical features: Appearance and colour: blue Odour: none Flash point: 340 °C Density at 20°C: from 900 to 990 Kg/m3 10. Stability and reactivity: Stable under normal conditions.
could increase the spread of flames. Combustion risks: Avoid smoke inhalation. Protection measures: Wear protective masks. 6. Measures to be adopted in case of accidental spread: Environmental precautions: Remove naked flares and any possible sources of combustion. Do not smoke. If the product has gone into a river, sewer or it has polluted either the ground, or vegetation, the authorities must be informed. Cleaning methods: Collect the product for re-cycling, if possible, or to dispose of it. Handling and storage: Handling precautions: Do not smoke during installation. Storage: Keep away from naked flames, sparks and heat sources. Precautionary measures: None. 9. Physical/chemical features: Appearance and colour: Do not smoke during installation. Storage: Keep away from naked flames, sparks and heat sources. Precautionary measures: None. 1. Appearance and colour: Do not smoke during installation. Storage: Keep away from naked flames, sparks and heat sources. Precautionary measures: None. 1. Appearance and colour: Do not smoke during installation. Storage: Keep away from naked flames, sparks and heat sources. None. 1. Provident in a river, sewer or it has polluted either the ground, or vegetation, the authorities must be informed. Cleaning methods: Collect the product for re-cycling, if possible, or to dispose of it. Handling precautions: Do not smoke during installation. Storage: Appearance and colour: Do not smoke. If any possible sources of combustion.
. Combustion risks: Avoid smoke inhalation Protection measures: Wear protective masks. 6. Measures to be adopted in case of accidental spread: . Environmental precautions: Remove naked flares and any possible sources of combustion. Do not smoke. If the product has gone into a river, sewer or it has polluted either the ground, or vegetation, the authorities must be informed Cleaning methods: Collect the product for re-cycling, if possible, or to dispose of it. 7. Handling and storage: Handling precautions: Do not smoke during installation Storage: Keep away from naked flames, sparks and heat sources. Precautionary measures: None. 9. Physical/chemical features: Appearance and colour: Odour: Odour: Odour: Odour: Odour: Odour: Odour: Odour: Odour: Office the product for re-cycling, if possible, or to dispose of it. Appearance and colour in one Flash point: Jensity at 20°C: From 900 to 990 Kg/m3 Conditions to be avoided: Stable under normal conditions.
. Protection measures: Wear protective masks. 6. Measures to be adopted in case of accidental spread: Remove naked flares and any possible sources of combustion. Do not smoke. If the product has gone into a river, sewer or it has polluted either the ground, or vegetation, the authorities must be informed. Cleaning methods: Collect the product for re-cycling, if possible, or to dispose of it. 7. Handling and storage: 1. Handling precautions: Do not smoke during installation. Storage: Keep away from naked flames, sparks and heat sources. 8. Control on exposure / personal protection: Precautionary measures: None. 9. Physical/chemical features: Appearance and colour: blue Odour: Odour: Density at 20°C: Density at 20°C: From 900 to 990 Kg/m3 10. Stability and reactivity: Stable under normal conditions.
Wear protective masks. 6. Measures to be adopted in case of accidental spread: Remove naked flares and any possible sources of combustion. Do not smoke. If the product has gone into a river, sewer or it has polluted either the ground, or vegetation, the authorities must be informed. Cleaning methods: Collect the product for re-cycling, if possible, or to dispose of it. 7. Handling and storage: None: None: 8. Control on exposure / personal protection: Precautionary measures: None. Appearance and colour: blue Odour: Odour
6. Measures to be adopted in case of accidental spread: Remove naked flares and any possible sources of combustion. Do not smoke. If the product has gone into a river, sewer or it has polluted either the ground, or vegetation, the authorities must be informed. Cleaning methods: Collect the product for re-cycling, if possible, or to dispose of it. 7. Handling and storage: Handling precautions: Do not smoke during installation. Storage: Keep away from naked flames, sparks and heat sources. Precautionary measures: None. 9. Physical/chemical features: Appearance and colour: blue Odour: none Flash point: 340 °C Density at 20°C: from 900 to 990 Kg/m3 10. Stability and reactivity: Conditions to be avoided: Stable under normal conditions.
Remove naked flares and any possible sources of combustion. Do not smoke. If the product has gone into a river, sewer or it has polluted either the ground, or vegetation, the authorities must be informed. Cleaning methods: Collect the product for re-cycling, if possible, or to dispose of it. Handling and storage: Handling precautions: Do not smoke during installation. Storage: Keep away from naked flames, sparks and heat sources. Precautionary measures: None. Precautionary measures: None. Appearance and colour: blue Odour: none Flash point: Ja40 °C Density at 20°C: from 900 to 990 Kg/m3 Conditions to be avoided: Stable under normal conditions.
Remove naked flares and any possible sources of combustion. Do not smoke. If the product has gone into a river, sewer or it has polluted either the ground, or vegetation, the authorities must be informed. Cleaning methods: Collect the product for re-cycling, if possible, or to dispose of it. Handling and storage: Handling precautions: Do not smoke during installation. Storage: Keep away from naked flames, sparks and heat sources. Precautionary measures: None. Precautionary measures: None. Appearance and colour: blue Odour: none Flash point: Ja40 °C Density at 20°C: from 900 to 990 Kg/m3 Conditions to be avoided: Stable under normal conditions.
Do not smoke. If the product has gone into a river, sewer or it has polluted either the ground, or vegetation, the authorities must be informed. Cleaning methods: Collect the product for re-cycling, if possible, or to dispose of it. Handling and storage: Handling precautions: Do not smoke during installation. Storage: Keep away from naked flames, sparks and heat sources. Precautionary measures: None. Physical/chemical features: Appearance and colour: Dodour: none Flash point: 340 °C Density at 20°C: from 900 to 990 Kg/m3 Conditions to be avoided: Stable under normal conditions.
If the product has gone into a river, sewer or it has polluted either the ground, or vegetation, the authorities must be informed. Cleaning methods: Collect the product for re-cycling, if possible, or to dispose of it. Handling precautions: Do not smoke during installation. Storage: Keep away from naked flames, sparks and heat sources. Precautionary measures: None. Physical/chemical features: Appearance and colour: Dodour: none Flash point: Ja40 °C Density at 20°C: Term 900 to 990 Kg/m3 Conditions to be avoided: Stable under normal conditions.
either the ground, or vegetation, the authorities must be informed. Cleaning methods: Collect the product for re-cycling, if possible, or to dispose of it. Handling and storage: Handling precautions: Do not smoke during installation. Storage: Keep away from naked flames, sparks and heat sources. Precautionary measures: None. Physical/chemical features: Appearance and colour: blue Odour: none Flash point: 340 °C Density at 20°C: from 900 to 990 Kg/m3 Conditions to be avoided: Stable under normal conditions.
. Cleaning methods: Collect the product for re-cycling, if possible, or to dispose of it. 7. Handling and storage: . Handling precautions: Do not smoke during installation Storage: Keep away from naked flames, sparks and heat sources. 8. Control on exposure / personal protection: Precautionary measures: None. 9. Physical/chemical features: . Appearance and colour: . Odour: . none . Flash point: . 340 °C . Density at 20°C: . Trom 900 to 990 Kg/m3 10. Stability and reactivity: . Conditions to be avoided: Stable under normal conditions.
Collect the product for re-cycling, if possible, or to dispose of it. 7. Handling and storage: Do not smoke during installation. Storage: Keep away from naked flames, sparks and heat sources. Precautionary measures: None. 9. Physical/chemical features: Appearance and colour: blue Odour: none Flash point: 340 °C Density at 20°C: from 900 to 990 Kg/m3 10. Stability and reactivity: Conditions to be avoided: Stable under normal conditions.
7. Handling and storage: Do not smoke during installation. Storage: Keep away from naked flames, sparks and heat sources. 8. Control on exposure / personal protection: None. 9. Physical/chemical features: Appearance and colour: blue Odour: Odour: Flash point: Flash point: Density at 20°C: Density at 20°C: Stable under normal conditions.
Do not smoke during installation. Storage: Keep away from naked flames, sparks and heat sources. Precautionary measures: None. 9. Physical/chemical features: Appearance and colour: Odour: none Flash point: Flash point: Density at 20°C: Tomp 900 to 990 Kg/m3 10. Stability and reactivity: Stable under normal conditions.
. Storage: Keep away from naked flames, sparks and heat sources. 8. Control on exposure / personal protection: . Precautionary measures: None. 9. Physical/chemical features: . Appearance and colour: . Odour: . none . Flash point: . Ja40 °C . Density at 20°C: . Density at 20°C: . Tom 900 to 990 Kg/m3 10. Stability and reactivity: . Stable under normal conditions.
. Storage: Keep away from naked flames, sparks and heat sources. 8. Control on exposure / personal protection: . Precautionary measures: None. 9. Physical/chemical features: . Appearance and colour: . Odour: . none . Flash point: . Ja40 °C . Density at 20°C: . Density at 20°C: . Tom 900 to 990 Kg/m3 10. Stability and reactivity: . Stable under normal conditions.
Keep away from naked flames, sparks and heat sources. Precautionary measures: None. Appearance and colour: blue Odour: none Flash point: 340 °C Density at 20°C: from 900 to 990 Kg/m3 Conditions to be avoided: Stable under normal conditions.
8. Control on exposure / personal protection: 9. Physical/chemical features: • Appearance and colour: • Odour: • none • Flash point: • Density at 20°C: • Density at 20°C: • Stable under normal conditions.
None. 9. Physical/chemical features: • Appearance and colour : blue • Odour : none • Flash point : 340 °C • Density at 20 °C : from 900 to 990 Kg/m3 10. Stability and reactivity : • Conditions to be avoided : Stable under normal conditions.
9. Physical/chemical features: . Appearance and colour : blue . Odour : none . Flash point : 340 °C . Density at 20 °C : from 900 to 990 Kg/m3 10. Stability and reactivity : . Conditions to be avoided : Stable under normal conditions.
. Odour: none . Flash point: 340 °C . Density at 20°C: from 900 to 990 Kg/m3 10. Stability and reactivity: Conditions to be avoided: Stable under normal conditions.
. Odour: none . Flash point: 340 °C . Density at 20°C: from 900 to 990 Kg/m3 10. Stability and reactivity: Conditions to be avoided: Stable under normal conditions.
. Flash point: 340 °C . Density at 20°C: from 900 to 990 Kg/m3 10. Stability and reactivity: Conditions to be avoided: Stable under normal conditions.
. Density at 20°C : from 900 to 990 Kg/m3 10. Stability and reactivity : . Conditions to be avoided : . Stable under normal conditions.
10. Stability and reactivity: Conditions to be avoided: Stable under normal conditions.
10. Stability and reactivity: Conditions to be avoided: Stable under normal conditions.
Stable under normal conditions.
L. Nildstances to be avoided ;
Avoid any contact with combustible materials. The product could
burn.
Avoid strong oxidizers and fluorine.
11. Toxicological information: . IARC (International Agency on Cancer Research):
Category 3. The substance is not classified as being dangerous to
man.
12. Environmental information: . Use in accordance with good working practices, dispose of
correctly.
Non biodegradable, non toxic for the environment.
13. Remarks on disposal: To be recycled if possible, in accordance with local and
•
national regulations.
14. Freight information: . On road (ADR): no limitations for freight
• On rail (RID): no limitations for freight
. By sea (IMO-IMDG): no limitations for freight
. By air (ICAO-IATA): no limitations for freight
• Category of danger VbF: not applicable
15. Rules: . None
15. Ruics.
16.00
16. Other information: . No other information available