



Cloud Hill Wind Farm

Volume 2a: EIA Report Figures excluding LVIA

August 2023

Project No.: 0669769

Page intentionally left blank

CONTENTS

1. INTRODUCTION

- **FIGURE 1.1** Site Location
- **FIGURE 1.2** Site Boundary Plan
- **FIGURE 1.3** Application Layout

2. EIA METHODOLOGY

- No Figures

3. SITE SELECTION AND DESIGN

- **FIGURE 3.1** Constraints Plan
- **FIGURE 3.2a** Site Design Evolution – Scoping
- **FIGURE 3.2b** Site Design Evolution – Pre-Chilled
- **FIGURE 3.2c** Site Design Evolution – Chilled
- **FIGURE 3.2d** Application Layout

4. DESCRIPTION OF THE PROPOSED DEVELOPMENT

- **FIGURE 4.1** Indicative Turbine Elevation
- **FIGURE 4.2** Indicative Foundation Design
- **FIGURE 4.3** Indicative Crane Hardstanding
- **FIGURE 4.4** Indicative Cable Trench Detail
- **FIGURE 4.5** Indicative Temporary Construction Compound

- **FIGURE 4.6** Indicative Substation Compound Layout
- **FIGURE 4.7** Indicative Control Building and Elevations
- **FIGURE 4.8** Indicative Windfarm Developers Control Building and Elevations
- **FIGURE 4.9** Indicative BESS Design and Elevations
- **FIGURE 4.10** Indicative Access Track
- **FIGURE 4.11** Indicative Culvert Detail
- **FIGURE 4.12.1** Indicative Borrow Pit Layout (a)
- **FIGURE 4.12.2** Indicative Borrow Pit Layout (b)
- **FIGURE 4.12.3** Indicative Borrow Pit Layout (c)
- **FIGURE 4.13** Indicative Met Mast Elevations

5. PLANNING AND ENERGY POLICY

- No Figures

6. LANDSCAPE AND VISUAL IMPACT ASSESSMENT

- Figures Included in Volume 2b and Volume 2c

7. ECOLOGY

- **FIGURE 7.1** Designated Sites and Ancient Woodland
- **FIGURE 7.2** Carbon Peatland
- **FIGURE 7.3** National Vegetation Classifications
- **FIGURE 7.4** Potential Groundwater Dependent Terrestrial Ecosystems
- **FIGURE 7.5a-b** Protected Species

- **FIGURE 7.5c** CONFIDENTIAL: Protected Species
- **FIGURE 7.6** Anabat Locations and Preliminary Bat Roost Assessment Results
- **FIGURE 7.7** Overall Risk Assessment 2020 (May-September) – Common Pipistrelle
- **FIGURE 7.8** Overall Risk Assessment 2020 (May-September) - Soprano Pipistrelle
- **FIGURE 7.9** Overall Risk Assessment 2020 (May-September) – Nyctalus Sp.
- **FIGURE 7.10** Electrofishing Locations and Survey Results
- **FIGURE 7.11** Biodiversity Enhancement Management Plan

8. ORNITHOLOGY

- **FIGURE 8.1** Vantage Points and Viewsheds
- **FIGURE 8.2** Survey and Study Areas
- **FIGURE 8.2.1** CONFIDENTIAL: Raptor and Owl Nest Locations
- **FIGURE 8.3** Designated Sites
- **FIGURE 8.4** Connectivity Distance Review
- **FIGURE 8.5** Black Grouse Lek Locations
- **FIGURE 8.6** Black Grouse Flight Activity
- **FIGURE 8.7** Raptor and Owl Flight Activity
- **FIGURE 8.8** Goshawk Flight Activity
- **FIGURE 8.9** Hen Harrier Flight Activity
- **FIGURE 8.10** Merlin Flight Activity
- **FIGURE 8.11** Osprey Flight Activity
- **FIGURE 8.12** Peregrine Flight Activity
- **FIGURE 8.13** Red Kite Flight Activity

- **FIGURE 8.14** Breeding Wader Activity
- **FIGURE 8.15** Curlew Flight Activity
- **FIGURE 8.16** Golden Plover Flight Activity
- **FIGURE 8.17** Pink-Footed Goose Flight Activity

9. **ARCHAEOLOGY AND CULTURAL HERITAGE**

- **FIGURE 9.1** Site Location and Study Areas
- **FIGURE 9.2** Heritage Assets within 1 km Study Area
- **FIGURE 9.3** *Prehistoric Heritage Assets*
- **FIGURE 9.4** *Medieval Heritage Assets*
- **FIGURE 9.5** *Post-Medieval Heritage Assets*
- **FIGURE 9.6** 1888 OS Map
- **FIGURE 9.7** 1937 OS Map
- **FIGURE 9.8** Designated Heritage Assets within 5 km
- **FIGURE 9.9** Designated Heritage Assets between 5-15 km: with Cumulatives
- **FIGURE 9.10** Designated Heritage Assets between 5-15 km: with Cumulatives - North West
- **FIGURE 9.11** Designated Heritage Assets between 5-15 km: with Cumulatives – North East
- **FIGURE 9.12** Designated Heritage Assets between 5-15 km: with Cumulatives – South East
- **FIGURE 9.13** Designated Heritage Assets between 5-15 km: with Cumulatives – South West

10. **GEOLOGY AND PEAT**

- **FIGURE 10.1** Bedrock Geology
- **FIGURE 10.2** Superficial Geology

- **FIGURE 10.3** National Soils Map of Scotland
- **FIGURE 10.4** Extract from Carbon and Peatland Map 2016
- **FIGURE 10.5** Interpolated Peat Depths

11. HYDROLOGY AND HYDROGEOLOGY

- **FIGURE 11.1** Hydrology Study Areas
- **FIGURE 11.2** Hydrological Catchment
- **FIGURE 11.3** Hydrological Features
- **FIGURE 11.4** Watercourse Crossings
- **FIGURE 11.5** Groundwater Dependent Terrestrial Ecosystems

12. NOISE

- **FIGURE 12.1** Cumulative Noise Contour Plot (Incl. Sanquhar 2)
- **FIGURE 12.2** Cumulative Noise Contour Plot (Excl. Sanquhar 2)
- **FIGURE 12.3** Noise Contour Plot

13. ACCESS, TRAFFIC AND TRANSPORTATION

- **FIGURE 13.1** Abnormal Load Route to Site
- **FIGURE 13.2** General Construction Traffic Route to Site
- **FIGURE 13.3** Traffic Count Locations
- **FIGURE 13.4a** RTC Assessment A70 - Between the A76 and Barr Quarries
- **FIGURE 13.4b** RTC Assessment A76 – Auchinleck to Sanquhar
- **FIGURE 13.4c** RTC Assessment A76 – Sanquhar to Barburgh Mill Quarry

- **FIGURE 13.5** Indicative Site Access Junction

14. SOCIO-ECONOMICS, TOURISM, RECREATION AND LAND USE

- **FIGURE 14.1** Recreational Route Maps
- **FIGURE 14.2** Recreational and Tourist Receptors Map
- **FIGURE 14.3** Southern Upland Way within the Site Boundary

15. CLIMATE CHANGE

- No Figures.

16. OTHER ISSUES

- **FIGURE 16.1** Shadow Flicker Casting Map

ERM has over 160 offices across the following countries and territories worldwide

Argentina	The Netherlands
Australia	New Zealand
Belgium	Norway
Brazil	Panama
Canada	Peru
Chile	Poland
China	Portugal
Colombia	Puerto Rico
France	Romania
Germany	Russia
Guyana	Singapore
Hong Kong	South Africa
India	South Korea
Indonesia	Spain
Ireland	Sweden
Italy	Switzerland
Japan	Taiwan
Kazakhstan	Tanzania
Kenya	Thailand
Malaysia	UK
Mexico	US
Mozambique	Vietnam
Myanmar	

ERM's Edinburgh Office

6th Floor
102 West Port
Edinburgh
EH3 9DN

www.erm.com